

F

30-045-27954

06-29-90

F. Loc. 2266/S; 1594/W Elev. 6078 GL Spd. _____ Comp. _____ TD _____ PB _____
 Cu. ft. _____ Cu. ft. _____ Cu. ft. _____
 Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. Pr. _____ @ _____ W _____ Sx. T. _____ @ _____ T Gas
 Csg. Perf. _____ Prod. Stim. _____

T
R
A
N
S

BO/D _____ Grav. _____ 1st Del. Gas
 I.P. _____ MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ 1st Del. Oil

TOPS	NiTD	X	Well Log	TEST DATA							Ref. No.
Ojo Alamo	C-103		Plat	X	Schd.	PC	Q	PW	PD	D	
Kirtland	C-104		Electric Log								
Fruitland			C-122								
Pictured Cliffs	Ditr		Dfa								
Chacra	Datr		Dac								
Cliff House											
Menefee											
Point Lookout											
Mancos											
Gallup											
Greenhorn											
Dakota											
Entrada											
	W/317.80 Acres										

P
o
o
BasinFrCoal Co. SJ S 28 T 31N R 10W UK Oper. Arco Oil & Gas Co. Lse. Atlantic Frt. 28 No. 2

Atlantic Fruitland 28 #2 K-28-31N-10W

ARCO OIL & GAS CO.

- ✓ 11. 1 Atlantic Fruitland 28, sec. 28, T. 31 N., R. 10 W., San Juan Co., NM, lease NM-0606.
- ✓ 12. 2 Atlantic Fruitland 28, sec. 28, T. 31 N., R. 10 W., San Juan Co., NM, lease NM-0606.
13. 1 Atlantic Fruitland 33, sec. 33, T. 31 N., R. 10 W., San Juan Co., NM, lease SF-080917.
14. 2 Atlantic Fruitland 33, sec. 33, T. 31 N., R. 10 W., San Juan Co., NM, lease SF-080917.
15. 1 Atlantic Fruitland 34, sec. 34, T. 31 N., R. 10 W., San Juan Co., NM, lease SF-080917.

As discussed with Ken Gosnell of your company on, September 26, 1991, the subject APDs are rescinded and returned due to drilling not being commenced within the approved period of time.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

John L. Keller
Chief, Branch of Mineral Resources

Enclosures

cc:

~~New Mexico Oil Conservation Division~~ 00 Rio Brazos Rd., Aztec, NM 87410