

F

30-045-28366

11-06-90

F. Loc. 1450/S; 1730/W

Elev. 6149 GL

Spd.

Comp.

ID

PB

Casing S. @ W Sx. Int. @ W Sx. Pr. @ W Sx. T. @

Csg. Perf. Prod. Stim.

T Gas  
R  
A  
N  
S

BO/D Grav. 1st Del. Gas

MCF/D After Hrs. SICP PSI After Days GOR 1st Del. Oil

| TOPS            |  | NITD X            | Well Log     | TEST DATA |    |   |    |    |   |          |
|-----------------|--|-------------------|--------------|-----------|----|---|----|----|---|----------|
|                 |  |                   |              | Schd.     | PC | Q | PW | PD | D | Ref. No. |
| Ojo Alamo       |  | C-103             | Plat X       |           |    |   |    |    |   |          |
| Kirtland        |  | C-104             | Electric Log |           |    |   |    |    |   |          |
| Fruitland       |  |                   | C-122        |           |    |   |    |    |   |          |
| Pictured Cliffs |  | Ditr              | Dfa          |           |    |   |    |    |   |          |
| Chacra          |  | Datr              | Dac          |           |    |   |    |    |   |          |
| Cliff House     |  | S/316.16<br>Acres |              |           |    |   |    |    |   |          |
| Menefee         |  |                   |              |           |    |   |    |    |   |          |
| Point Lookout   |  |                   |              |           |    |   |    |    |   |          |
| Mancos          |  |                   |              |           |    |   |    |    |   |          |
| Gallup          |  |                   |              |           |    |   |    |    |   |          |
| Greenhorn       |  |                   |              |           |    |   |    |    |   |          |
| Dakota          |  |                   |              |           |    |   |    |    |   |          |
| Entrada         |  |                   |              |           |    |   |    |    |   |          |
|                 |  |                   |              |           |    |   |    |    |   |          |

p  
o  
o

Basin Fr. Coal Co. SJ S 09 T 31N R 10W U K Oper. Meridian Oil, INC. Les. Lucerne A No. 102

Lucerne A #102

K-09-31N-10W

MERIDIAN OIL, INC.



# United States Department of the Interior

BUREAU OF LAND MANAGEMENT  
Farmington Resource Area  
1235 Laplata Highway  
Farmington, New Mexico 87401

TAKE  
PRIDE IN  
AMERICA

IN REPLY REFER TO:  
SF-078389 et al. (WC)  
3162.3-1.0 (019)

DEC. 4 1991

**RECEIVED**

DEC 5 1991

**OIL CON. DIV  
DIST. 3**

Meridian Oil Inc.  
PO Box 4289  
Farmington, NM 87499

Gentlemen:

Enclosed are your Applications for Permit to Drill the following wells:

- ✓ 1. No. 101 Lucerne A Com, Sec. 9, T. 31 N., R. 10 W., San Juan County, New Mexico, lease SF-078389.
- ✓ 2. No. 265 Rosa Unit, Sec. 27, T. 31 N., R. 5 W., Rio Arriba County, New Mexico, lease SF-078770.
- ✓ 3. No. 500 Summit Viles, Sec. 33, T. 29 N., R. 11 W., San Juan County, New Mexico, lease SF-047019-A.
- ✓ 4. No. 213 San Juan 32-9 Unit, Sec 14, T. 31 N., R. 10 W., San Juan County, New Mexico, lease NM-01594.
- ✓ 5. No. 102 Lucerne A, Sec 9, T. 31 N., R. 10 W., San Juan County, New Mexico, lease SF-078389.
- ✓ 6. No. 100 Lucerne A, Sec 3, T. 31 N., R. 10 W., San Juan County, New Mexico, lease SF-078389.
- ✓ 7. No. 500 Angel Peak B, Sec 13, T. 28 N., R. 11 W., San Juan County, New Mexico, lease SF-047017-A.
- ✓ 8. No. 101 East, Sec 25, T. 31 N., R. 12 W., San Juan County, New Mexico, lease SF-077652.
- ✓ 9. No. 8R Atlantic A, Sec 29, T. 31 N., R. 10 W., San Juan County, New Mexico, lease NM-0606.

As discussed with Peggy Bradfield of your company on, November 20, 1991, the subject APDs are rescinded and returned due to drilling not being commenced within the approved period of time.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that

## ABANDONED LOCATION

construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

John L. Keller  
Chief, Branch of Mineral Resources

9 Enclosures

cc:  
New Mexico Oil Conservation Division, Aztec, NM