UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

which would entitle the applicant to conduct operations thereon.

fraudulent statements or representations as to any matter within its jurisdiction.

RECEIVED BLM

FORM APPROVED OMB No. 1004-0135 EXPIRES: July 31, 1996

SUNDRY NOTICES AND REPORTS ON WELLS NM83503 Do not use this form for proposals to drill or to deepen or re-enter ap 1/2: 32 s. if Indian, Allottee or Tribe Name abandoned well. Use form 3160-3 (APD) for such proposals. ther instruction on reverse side 070 FARMINGTON, 1. Type of Well 7. If Unit or CA/ Agreement, Name and/or No. OR WAR X Gas Well Other 2. Name of Operato **CNG PRODUCING COMPANY** 3a Address 3b. Phone No. (include area cobe) (504) 593-7000 1450 POYDRAS ST, NEW ORLEANS, LA 70112-6000 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) d and Pool, or Exploratory Area 624' FSL & 507' FNL of Sec. 30-T32N-R7W San Juan, New Mexico 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Production (Start/Resume) WEEKLY REPORT OF OPERATIONS Final Abandonment Notice 13 Describe Proposed or Completed Operations (Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duratio if the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers an Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 day following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed o testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation have been completed, and the operator determined that the site is ready for final inspection.) SUMMARY OF OPERATIONS SEPTEMBER 19, 1998 - SEPTEMBER 25, 1998 Worked drill pipe from 3,645 to 3,707 cleaning coal samples and circulating fill tat continues to fall in from the side walls of the hole. Cleaned hole from 3,707 3,770°. Turned off air and mist. Tripped up to 7" shoe, natural blow for 4 hours. Tripped back and tagged fill at 3,555°. Cleaned hole to 3,614' to 3,738°. Plugged bit on connection to clean to TD. Trip out of hole - unplugged bit. Trip in hole and tag fill at 3,480°. Put air/mist system on hole and clean to 3,770°. Hole cleaning up well. No bridges lest 93' but considerable fill that was washed and rotated to get down into. Cleaned hole at TD, increased scap/form concentration for additional cleaning capacity. Made short trip to 3,491'. Trip back, tag at 3,595'. Circulate large volumes of coal. Worked drill pipe back to 3,645'. Cleaned hole 3,676' to 3,770'. Short trip to 3,491'. Trip back and tag at 3,620'. Cut drilling line. Trip back and tag at 3,560'. Increased air in stages while cleaning down to 3,770'. Estimated gas rate ±2.5 to 2.7 MMCF/D. Cleaned hole at TD with 1400 SCFPM air. Made short trip to 3,491'. Trip back and tag at 3,605°. Worked drift pipe through bridge plug to TD. Trip out of hole. Rig up to run 5 1/2" liner. Tag at 3,480°. Washed and rotated liner to TD using 2500 SCFPM air. Set liner hanger slips and pack off. Trip out of hole laying down drill pipe. 14. I hereby certify that the forgoing is true and correct Name (Printed/Typed) Title SUSAN H. SACHITANA REGULATORY REPORTS ADMINISTRATOR Date 980925 Approved by **ACT 0 6 1998** Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject less FARMINGTON DISTRICT OFFICE

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious