

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT - " for such proposals

RECEIVED
JUL 8 1993
OIL COAL DIV.

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

AMOCO PRODUCTION COMPANY

Attention:

Pat Archuleta

3. Address and Telephone No.

P.O. BOX 800 DENVER, COLORADO 80201

303-830-5217

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1430' FNL

1540' FEL

Sec. 34 T 31N R 9W

UNIT G

5. Lease Designation and Serial No.

NM-013686

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Pritchard C

#1

9. API Well No.

3004528622

10. Field and Pool, or Exploratory Area

Basin Fruitland Coal

11. County or Parish, State

SAN JUAN

NEW MEXICO

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other Well Service

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MIRUSU 5/21/98.

Ran 2.43 guage ring and set tbq plug forth at 2800', after setting tbq plug nnd wh nubop and tin tag bit sub top at 2849' and toh w/2.97 prod tbq.

New tbq string is tapered 2.875 by 2.375 and end sa 2811', bottom joint is a 20' mule shoe joint with a 5/8 hole in the top for gas discharge. Layed down 18 jts of 2.875 tbq and two 10' subs along w/slotted sub and purge valve.

After landing tapered tbq string nd bop nu wh and pull tbq plug from conversion collar at seating nipple and run rods.

After seating pump, stroke pump and test seat and tbq to 500 psi and held okay. Place well back on production w/pmp intake below bottom peerforation and no fill in rat hole.

RDMOSU 5/26/98.

14. I hereby certify that the foregoing is true and correct

Signed

Pat Archuleta

Title

Staff Assistant

Date

08-08-1998

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

Date

JUN 30 1998

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious, or fraudulent statements or representations as to any matter within its jurisdiction.

* See Instructions on Reverse Side

NMOC

RECEIVED
BLM
070 FAIRMONT, NM
98 JUN 14 PM 1:29
ACCEPTED FOR RECORD
JUN 30 1998
ADMINISTRATIVE DISTRICT OFFICE