UNITED STATES

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

DEPARTMENT OF T	HE INTERIOR	X
BUREAU OF LAND M	IANAGEMENT	5. Lease Designation and Serial No. 14-20-603-2022
SUNDRY NOTICES AND R	EPORTS ON WELLS	6. If Indian, Allottee or Tribe Name
Do not use this form for proposals to drill or to de		Navajo
Use "APPLICATION FOR PERM	IT" for such proposals	
		7. If Unit or CA, Agreement Designation
SUBMIT IN TRI	DI ICATE	
	ILICATE	Horseshoe Gallup Unit
1. Type of Well		8. Well Name and No.
X Oil Gas Other		Horseshoe Gallup No. 303
2. Name of Operator		9. API Well No.
Vantage Point Energy 3. Address and Telephone No. (7	13) 780-1952	
Suite 700, 2401 Fountain View Drive, Hous	•	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey D	escription)	Horseshoe Gallup
		11. County or Parish, State
1840' FNL x 645' FEL Section 23, T31	N, R17W	San Juan County, NM
TO DO THE DOWN TO A	MOTO THE STATE OF MOMICE DI	EDODE OF OTHER DATA
12. CHECK APPROPRIATE BOX(s) TO I	INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION	
TYPE OF SUBMISSION		
X Notice of Intent	X Abandonment	☐ Change of Plans
	\square Recompletion	☐ New Construction
Subsequent Report	☐ Plugging Back	Non-Routine Fracturing
`	Casing Repair	☐ Water Shut-Off
		_
Final Abandonment Notice	Altering Casing	☐ Conversion to Injection
	Other	Dispose Water (Note: Report results of multiple completion on Well
		Completion or Recompletion Report and Log form)
 Describe Proposed or Completed Operations (Clearly proposed work. If well is directionally drilled, give st this work.)* 	state all pertinent details, and give pertinent da ibsurface locations and measured and true verti	tes, including estimated date of starting any cal depth for all markers and zones pertinent to
See Attached P & A Procedure.		
	Arrest of the strategic and sent are as a section of the section o	an per ang managanahan manaman and menang and a figure of the contract of the
The proposed work is scheduled to occur	on or before July 15, 1995.	-
	DEAGA	#PD
	미르당립시	() BIN The state of the state
	kn(—) — .	- IVI
	EB 2 1 1	995
		74 ús
	OIL COM.	DIM
	DIST. 3	
14. I hereby certify that the foregoing is true and correct	Englic 6	1
C - 1		
Signed Color	Title Consultant for Vantage Poi	nt Energy Date February 14, 1995
(This space for Federal or State office use)		
		_
Approved by	Title	Date
Conditions of approval, if any:		

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. *See Instruction on Reverse Side

FEB 1 1 1995

Plugging and Abandonment Procedure

Horseshoe Gallup Unit No. 303

Well Data

Location:

1840' FNL x 645' FEL, Section 23, T31N, R17W

San Juan County, New Mexico

Lease No.:

14-20-603-2022

TD:

1656 ft (1/2/92)

PBTD: 1624 ft

Surface Csg:

8 5/8", 24 ppf, J-55, STC @ 136 ft. 12 1/4" hole dia. Cmt w/ 85 sks 'B'.

Circ to surface.

Production Csg:

5 1/2", 14 ppf, J-55, STC @ 1638 ft. 7 7/8" hole dia. Cmt w/ 200 sks

65/35 POZ and 50 sks 'G'. Circ 50 sks to surface.

Perforations:

Lower Gallup, 1532 - 1548, 1523 - 1529 @ 4 jspf (88 perfs)

Procedure

1. Prepare Location. Check anchors.

- 2. MIRU Pulling unit. Unit to be equipped with pump and tank. NU 2000 psi BOPE.
- 3. Pick up 2 7/8" tbg. Strap in hole to PBTD of 1624 ft.
- 4. Mix 30 sks Class 'b' neat slurry (yield 1.15 cf/sk). Spot balanced cement plug from 1624 ft to 1400 ft. Pull out of cement slowly. Pull up to 1000 ft and reverse out tubing. Circulate into rig tank. WOC 2 hours.
- 5. RIH and tag plug.
- 6. Mix 170 sks Class 'b' neat slurry. Place second plug from 1400 ft to surface.
- 7. POOH laying down tubing.
- 8. Cut off well head and casing
- 9. Install cap and dry hole marker.
- 10. Reclaim location as per BLM regulations.