

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Submit 3 Copies
to Appropriate
District Office

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
600 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-045-28855
5. Indicate Type of Lease LEASE ☐ FREE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Nickles 11
8. Well No. 2
9. Pool name or Wildcat Basin Fruitland Coal

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
Hallwood Petroleum, Inc.

3. Address of Operator
P. O. Box 378111, Denver, CO 80237

4. Well Location
Unit Letter L : 1850 Feet From The South Line and 790 Feet From The West Line

Section 11 Township 31N Range 13W NMPM San Juan County

10. Elevations (Show whether LF, RKB, RT, GR, etc.)

5702 KB 5690 GL

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRUSU, pull rods & pump (laydown) ND tree x NU BOP, pull tbg (stand back).
2. PU a 5 1/2" 17# retainer & TIH w/tbg to just above perfs at 1810'.
3. Pump 200 sks of cement below retainer.
4. Pull out of retainer spot a 25 sack (210 foot) cement plug from 1810' to 1600'.
5. Pull tbg to 1170' & balance a 25 sack (210 foot) cement plug across OJO Alamo Top at 1070'.
6. Pull tbg to 375' and spot a 15 sack (125 foot) cement plug across shoe.
7. Spot a 10 sack surface plug, cut off 5 1/2" head, set dry hole marker, RDSU, pull anchors and restore location.

* Plug between Kirtland and RDSU

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Nonya K. Durham TITLE Production Technician DATE 12/20/94
TYPE OR PRINT NAME Nonya K. Durham TELEPHONE NO 303-850-621

(This space for State Use)

APPROVED BY Johnny Robinson TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #3 DATE 2 2 1994
CONDITIONS OF APPROVAL, IF ANY: As noted above