

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved,
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR
E P Operating Company

3. ADDRESS OF OPERATOR
1700 Lincoln St., Ste. #3600, Denver, CO 80203

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
2180' FNL, 2300' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether dr., K.B., or G.L.)
6435' K.B., 6423' G.L.

5. LEASE DESIGNATION AND SERIAL NO.
NM-4282

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
N/A

7. UNIT AGREEMENT NAME
N/A OIL CON. DIV. 1

8. FARM OR LEASE NAME
Federal DIST. 3

9. WELL NO.
#1-30

10. FIELD AND POOL, OR WILDCAT
Ute Dome (Penn)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 30, T32N, R13W

12. COUNTY OR PARISH
San Juan

13. STATE
New Mexico

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	REPAIRING WELL	<input checked="" type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

The Federal #1-30 has been shut-in since March, 1986 due to curtailment. Recently E P Operating Company (EPOC) has attempted to return the well to production on several occasions.

November 19-21, 1986 EPOC blew well down in 30 minutes. In an attempt to swab well, the sand line parted leaving approximately 2800' in the hole.

December 2-11, 1986 EPOC blew well down and recovered swab line. Attempted to jet the well in with coiled tubing unit without success. Recovered approximately 45 barrels load water during jetting.

December 17-20, 1986 EPOC blew well down and commenced to try and swab well in for four (4) days, recovering approximately 530 barrels water.

The well currently remains shut-in pending engineering evaluation and recommendation. Subsequent reports to return the well to production will be submitted as they occur.

Form C-103 submitted to State of New Mexico on 1/12/87

18. I hereby certify that the foregoing is true and correct

SIGNED Greg Benton

TITLE Assoc. Petroleum Engineer

DATE 1/12/87

ACCEPTED FOR RECORD

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE 1/23/1987

FARMINGTON RESOURCE AREA

BY SPM

*See Instructions on Reverse Side

WMOCC