


(SUBMIT IN TRIPLICATE)

Land Office **Santa Fe**  
Lease No. **079224-1**  
Unit **San Juan Unit 32-5**



UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			
<b>Notice of Intention to Work Over</b> <input checked="" type="checkbox"/>			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 27th, 1958

Well No. **1-10** is located **1850** ft. from **[N]** line and **1450** ft. from **[E]** line of sec. **10**

**NE/4 SW/4 Sec. 10** **32N** **5W** **K.M.P.M.**  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
**Wilcox** **Bio Arriba** **New Mexico**  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **7577** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

**Present total depth 4214' with 5-1/2" casing set at 4211'.  
Two snubbing strings were lost in hole in October of 1957, and location temporarily abandoned. It is now proposed to attempt to recover the snubbing strings and test the well in the Pictured Cliffs formation.**

**ILLEGIBLE**

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **LA PLATA CATERING SYSTEM, INC.**

Address **1900 Mercantile Bank Building  
Dallas 1, Texas**

By *[Signature]*  
Title **Engineer**