

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Indian Agency Navajo  
1-149-III-7633  
Allottee \_\_\_\_\_  
Lease No. \_\_\_\_\_

	X	

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	X	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 30, 19 59

Well No. Navajo is located 1970 ft. from N line and 1460 ft. from E line of sec. 4

SE NW Sec. 4 (1/4 Sec. and Sec. No.)	30N 17W (Twp.) (Range)	MM PM (Meridian)
<u>Undesignated</u>	<u>San Juan</u>	<u>New Mexico</u>
(Field)	(County or Subdivision)	(State or Territory)

The elevation of the derrick floor above sea level is 5102 ft.

DETAILS OF WORK


(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled 6 1/2" hole to 1087

Top of Gallup 446  
Top of Dakota 1025

Ran 1087' 4 1/2" casing and cemented w/40 sz.

Plan to perforate and test.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company King Oil Company

Address 745 Petroleum Club Bldg.  
Denver, Colorado

By Bernard King  
Title President

