

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/> Federal <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator <b>El Paso Natural Gas Company</b>	8. Farm or Lease Name <b>Florance</b>
3. Address of Operator <b>Box 990, Farmington, New Mexico</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>A</b> , <b>990</b> FEET FROM THE <b>North</b> LINE AND <b>990</b> FEET FROM THE <b>East</b> LINE, SECTION <b>24</b> TOWNSHIP <b>30N</b> RANGE <b>10W</b> NMPM.	10. Field and Pool, or Wildcat <b>Blanco Mesa Verde</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>6221' KB</b>	12. County <b>San Juan</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is intended to perform the following work to improve the mechanical condition of the well and to increase productivity. Estimated commencement date is 4-24-65:

1. Test 7" casing and repair leaks by squeezing cement or perforate opposite the base of the Ojo Alamo and squeeze w/cement.
2. Clean out the open hole, set and cement a string of 4 1/2" production casing, selectively perforate and sand-water fracture the Mesa Verde.
3. Clean out the well and run tubing.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Original Signed F. H. WOOD</u>	TITLE <u>Petroleum Engineer</u>	DATE <u>4-20-65</u>
APPROVED BY <u>Emily Chandler</u>	TITLE <u>Sup Dist III</u>	DATE <u>4-21-65</u>
CONDITIONS OF APPROVAL, IF ANY:		