REESE MESA # 103 J-11-32N-8W

SOUTHLAND ROYALTY CO.

F. loc	2435/S;2080E				Elev	060 GL	Sad	Co			<b>TO</b>		_	
	@w <sup>.</sup>		Cu. ft Sx.	Int		w	Spd Cu. ft. Sx. Pr Prod. Stim.	Comp			DCu. ft. SxT	P		† Gas
1.P	BO/D MCF/D	After	Hrs. Si	ICP	PSI	After	Grav Days GOR		1st De	I. <u>Gas</u>				A N S
TOPS			NITO X		Well Log		TEST DATA							
Ojo Alamo			C-103		· /	Plat X	<b>V</b> V	Schd.	PC	Q	PW	PD	D	Ref.No.
Kirtland			C-104			Electric Log			<u> </u>				<del>-</del>	K#1.140.
Fruitland						C-122					<del> </del> -		<del> </del>	<del> </del>
Pietured Cliffs		.,,	Ditr			Dfa			<del> </del>	·	<del></del> -			<del> </del>
Chacra			Datr			Doc						<b>-</b>		<del> </del>
Cliff House						iL				<del></del>	<del> </del>			<del> </del>
Menefee														<u> </u>
Point Lookout								<del></del>			<del> </del>			<u> </u>
Mancos	$\top$	-	,								ļ			<b>↓</b>
Gallup	+				1		-							<b></b>
Greenhorn	+				,									<u> </u>
Dakota			]			1.50 - R -91	U55 299.89							<u> </u>
Entrada	_		ł		•	10.76	154-2562							<u> </u>
						•								
	l		L				Acres 157.26 394.30							

R-8768



## United States Department of the Interior

BUREAU OF LAND MANAGEMENT **FARMINGTON RESOURCE AREA** 1235 LAPLATA HIGHWAY **FARMINGTON, NEW MEXICO 87401** 



IN REPLY REFER TO:

SF-078487 (WC) 3162.3-1.0 (019)

CERTIFIED - RETURN RECEIPT REQUESTED P 253 046 165

DEC. 1 3 1990

Southland Royalty Company P.O. Box 4289 Farmington, NM 87499

## Gentlemen:

Enclosed are your Applications for Permit to Drill (APDs) for the following wells:

- No. 200 Hudson Com, SW/4SW/4 sec. 17, T. 31 N., R. 10 W., San Juan County, New Mexico, lease SF-078134.
- No. 103 Trail Canyon, SE/4NE/4 sec. 18, T. 32 N., R. 8 W., San Juan County, New Mexico, lease NM-33055.
- 3. No. 103 Reese Mesa, NW/4SE/4 sec. 11, T. 32 N., R. 8 W., San Juan County, New Mexico, NM-6890.
- 4. No. 210 Hill, SE/4NE/4 sec. 4, T. 29 N., R. 8 W., San Juan County, New Mexico, lease SF-078487.

As discussed with Peggy Bradfield of your company on October 12, 1990, the subject APDs are rescinded and returned due to drilling not being commenced within one year of the approval date and within the second six month extension period.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, it will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

## ABANDONED LOCATION John L. Keller

Ron Fellows Area Manager

OIL CON, DIS DIST. 3

cc:

NMOCD, 1000 Rio Brazos Road, Aztec, NM 87410