District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

State of New Mexic RECEIVED

Energy Minerals and Natural | By Jamie at 7:19 am, Sep 23, 2015

Oil Conservation Division 1220 South St. Francis Dr.

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back

1220 S. St. Francis Dr., Sonto Fe, NM 87505 Santa Fe, NM 87505 side												side of form		
			Rele	ease Notific	cation	and Co	rrective A	ction						
						OPERA'	FOR	Г	7 Initia	l Report	\boxtimes	Final Report		
		CCIDENTA		AN LTD.		Contact JOEY RODGERS								
		nolind Road,					No. (806)592-73							
Facility Nar	ne NORT	H HOBBS L	INIT RC	F/WIB		Facility Typ	e OIL AND GA	S PROD	UCTIO	N FACILI	TY			
Surface Ow	ner Occid	ental Permia	n LTD.	Mineral (Owner I	HOBBS (G-SA) Lease No.								
				LOCA	ATIO	ON OF RELEASE								
Unit Letter H	Section 25	Township 18-S	Range 37-E	Feet from the	North/	South Line	Feet from the	East/We	st Line	County Lea				
	Latitude <u>32°43'14.96"</u> Longitude <u>103°11'59.65"</u>													
	NATURE OF RELEASE													
Type of Rele							Release 315 MCI			ecovered 0				
Source of Re RCF FLARE		NTS					our of Occurrence			lour of Dis				
Was Immedia						If YES, To	2:39:00 PM Whom?	8	/14/2015	2:39:00 PN	1			
			Yes [No 🗵 Not R	equired		***************************************							
By Whom? N	}A_					Date and I-	lour NA							
Was a Water	course Read	hed?		If YES, Ve	lume Impacting t	he Waterc	ourse.							
	irse was Im	pacted, Descr	ibe Fully.	;		1								
	NA .													
Describe Cau Cause:	se of Probl	em and Reme	dial Action	Taken.*										
INTERMITT CYLINDER	ENT FLAF HIGH TEN	UNG AT NO	RTH HOB	BS UNIT REINI	ECTION	N COMPRES	SOR FACILITY	(RCF). E	TRAIN S	SHUT DOV	VN ON	#2		
Remedial Act			– – – –									1		
MAINTENA Describe Are	NCE REPA	MRED THE E	Action Tol	AND OPERATION *	ONS RE	STARTED 1	HE COMPRESS	OR.						
NONE		and Cicanop i	teron tak	M. 1.										
Lhereby certi	fy that the i	nformation ai	ven abova	is true and comm	late to th	a best of mu	transladas and su	-444	Albana anna	ND 4	000			
regulations al	l operators	are required to	report an	d/or file certain r	elease no	ie ocst of my otifications a	knowledge and ui	naersiana tive action	that pursi is for rele	BBI IO NM BSCS Which	may cr	ules and		
public nealth	or the envi	ronment. The	acceptanc	e of a C-141 repo	ort by the	: NMOCD m	arked as "Final Ro	enoria que	s not relic	eve the one	rator of	linbility		
should their o	perations h	ave failed to a	dequately	investigate and r	emediate	: contaminati	on that pose a thre	eat to grou	ind water.	surface wa	iter hio	man bealth		
federal, state.	or local lay	vs and/or regu	Iduaccep Ilations	tance of a C-141	report do	ocs not reliev	e the operator of r	esponsibil	lity for co	mpliance w	/ith any	other		
	~/	\sim					OIL CONS	SERVA	TION	DIVISIO	 N			
Signature:	- Xx	V -				OIL CONSERVATION DIVISION								
Printed Name	: JOEY-RO	DOGERS				Approved by	District Supervise	or: Jan	n¥lhye					
Title: HES O	PS ADVIS	OR				Approval Dat	09/23/2015	Ex	piration [)// Pate:				
E-mail Addre	ss: joey ro	dgers@oxy.co	m			Conditions of Approval:								

08/17/2015

////

Phone: (806)592-7311

1RP 3873

District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1300 Rio Brazos Road, Aztec, NM 87410 District IV District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

* Attach Additional Sheets If Necessary

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action OPERATOR Initial Report Serial Report Address 1017 W. Stanolind Road, Hobbs Telephone No. (806)592-7311 Facility Name North Hobbs Unit Ref/Wib Facility Type Oll AND GAS PRODUCTION FACILITY Surface Owner Occidental Permian LTD. Mineral Owner Hobbs (G-SA) Lease No. LOCATION OF RELEASE Unit Letter Section Township Range 18-S 37-E Feet from the North/South Line Feet from the East/West Line County Lea Latitude 32°43' 14.96" Longitude 103°11'59.65" NATURE OF RELEASE Type of Release Gas Volume of Release 106 MCF Volume Recovered 0 Source of Release Gas Source of Release No. Latitude 32°43' 14.96" Longitude 103°11'59.65" NATURE OF RELEASE Type of Release Gas Volume of Release 106 MCF Volume Recovered 0 Source of Release Male Notice Given? If Yes No Not Required Not Required Notice Given? If Yes Not Not Required Not Report Not Not Not Not Required Not Report Not Not Not Required Not Report Not Not Not Required Not Report Not Not Not Not Required Not Report Not Not Not Not Not Not Required Not Report Not Not Not Not Not Not Not Not Not No	TO T THE A STATE OF THE STATE O									
Name of Company OCCIDENTAL PERMIAN LTD. Address 1017 W. Stanolind Road, Hobbs Telephone No. (806)592-7311 Facility Name NORTH HOBBS UNIT RCF/WIB Surface Owner Occidental Permian LTD. Mineral Owner HOBBS (G-SA) Lease No. LOCATION OF RELEASE Unit Letter Section Township 18-8 37-E Indicated 32-43'14.96" Longitude 103'11'59.65" NATURE OF RELEASE Volume of Release Gas Source of Release RCF FLARE SSM EVENTS Was immediate Notice Given? Yes No Not Required By Whon? NA Was a Watercourse Reached? Yes No Date and Hour NA If YES, Volume Impacting the Watercourse. NA If a Watercourse was Impacted, Describe Fully.* NA Describe Cause of Problem and Remedial Action Taken. * Cause: FLARED AT NORTH HOBBS UNIT REINJECTION COMPRESSOR FACILITY (RCF). C TRAIN WENT DOWN DUE TO LOW OIL PRESSURE SHUTD DWN. Remedial Action Taken: OPERATIONS CHANGED FILERS AND CHECKED THE AUXILIARY OIL SYSTEM. COMPRESSOR WAS RESTARTED AFTER CHECKS. Describe Area Affected and Cleanup Action Taken. * NONE	Release Notification	ion and Corre	ective Action	n						
Name of Company OCCIDENTAL PERMIAN LTD. Address 1017 W. Stanoind Road, Hobbs Facility Name NORTH HOBBS UNIT REFIVIB Facility Name NORTH HOBBS UNIT REFIVIB Facility Name NORTH HOBBS UNIT REFIVIB Surface Owner Occidental Permian LTD. Mineral Owner HOBBS (G-SA) Lease No. LOCATION OF RELEASE Unit Letter Section Township 18-S 37-E Latitude 32°43'14.96" Longitude 103°11'59.65" NATURE OF RELEASE Volume of Release Gas Source of Releas		OPERATOR	R	Initia	Report	\boxtimes	Final Report			
Surface Owner Occidental Permian LTD. Mineral Owner HOBBS (G-SA) Lease No.		Contact JOEY R	ODGERS							
Surface Owner Occidental Permian LTD. Mineral Owner HOBBS (G-SA) Lease No. LOCATION OF RELEASE Unit Letter Section 25 18-S 17-E Feet from the North/South Line Feet from the East/West Line County Lea Latitude 32°43' 14.96" Longitude 103° 11'59.65" NATURE OF RELEASE Type of Release Gas Volume of Release 106 MCF Volume Recovered 0 Source of Release SM EVENTS Date and Hour of Occurrence Date and Hour of Discovery 8/17/2015 8:55:00 AM 8/17/2015 8:55:00 AM 8/17/2015 8:55:00 AM Was Immediate Notice Given? If YES, To Whom? NA Date and Hour NA If YES, Volume Impacting the Watercourse. NA Was a Watercourse was Impacted, Describe Fully.* NA Describe Cause of Problem and Remedial Action Taken.* Cause: FLARED AT NORTH HOBBS UNIT REINJECTION COMPRESSOR FACILITY (RCF). C TRAIN WENT DOWN DUE TO LOW OIL PRESSURE SHUT DOWN. Remedial Action Taken: PLARED AT NORTH HOBBS UNIT REINJECTION COMPRESSOR FACILITY (RCF). C TRAIN WENT DOWN DUE TO LOW OIL PRESSURE SHUT DOWN. Remedial Action Taken: PLARED AT NORTH HOBBS UNIT REINJECTION COMPRESSOR FACILITY (RCF). C TRAIN WENT DOWN DUE TO LOW OIL PRESSURE SHUT DOWN. Remedial Action Taken: PLARED AT NORTH HOBBS UNIT REINJECTION COMPRESSOR FACILITY (RCF). C TRAIN WENT DOWN DUE TO LOW OIL PRESSURE SHUT DOWN. Remedial Action Taken: PLARED AT NORTH HOBBS UNIT REINJECTION COMPRESSOR FACILITY (RCF). C TRAIN WENT DOWN DUE TO LOW OIL PRESSURE SHUT DOWN. Remedial Action Taken: PLARED AT NORTH HOBBS UNIT REINJECTION COMPRESSOR FACILITY (RCF). C TRAIN WENT DOWN DUE TO LOW OIL PRESSURE SHUT DOWN. Remedial Action Taken: PLARED AFTER CHECKS. Describe Area Affected and Cleanup Action Taken.*										
Latitude 32°43'14.96" Longitude 103°11'59.65"	Facility Name NORTH HOBBS UNIT RCF/WIB	Facility Type OI	L AND GAS PRO	ODUCTION	Y FACILIT	Υ				
Unit Letter Section Township Range 37-E Feet from the North/South Line Feet from the East/West Line County Lea Latitude 32°43'14.96" Longitude 103°11'59.65" NATURE OF RELEASE	Surface Owner Occidental Permian LTD. Mineral Owne	r HOBBS (G-SA) Lease No.								
Unit Letter Section Township Range 18-S 17-E Fect from the North/South Line Feet from the East/West Line County Lea			ASE							
Latitude 32°43'14.96" Longitude 103°11'59.65" NATURE OF RELEASE Type of Release Gas Volume of Release 106 MCF Obta and Hour of Occurrence RCF FLARE SSM EVENTS Was Immediate Notice Given? Yes No Not Required By Whom? NA Date and Hour NA If YES, To Whom? NA Date and Hour NA If YES, Volume Impacting the Watercourse. NA If a Watercourse was Impacted, Describe Fully. NA Describe Cause of Problem and Remedial Action Taken. Cause: Describe Cause of Problem and Remedial Action Taken. Describe Area Affected and Cleanup Action Taken. Describe Area Affected and Cleanup Action Taken. Thereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger				West Line	County					
Type of Release Gas Volume of Release 106 MCF Volume Recovered 0 Source of Release RCF FLARE SSM EVENTS Was Immediate Notice Given? Yes No Not Required By Whom? NA Was a Watercourse Reached? Yes No Not Required If YES, To Whom? NA Date and Hour of Occurrence 8/17/2015 8:55:00 AM If YES, To Whom? NA Was a Watercourse Reached? Yes No Not Required If YES, Volume Impacting the Watercourse. NA If YES, Volume Impacting the Watercourse. NA Describe Cause of Problem and Remedial Action Taken.* Cause: FLARED AT NORTH HOBBS UNIT REINJECTION COMPRESSOR FACILITY (RCF). C TRAIN WENT DOWN DUE TO LOW OIL PRESSURE SHUT DOWN. Remedial Action Taken: OPERATIONS CHANGED FILTERS AND CHECKED THE AUXILIARY OIL SYSTEM. COMPRESSOR WAS RESTARTED AFTER CHECKS. Describe Area Affected and Cleanup Action Taken.* NONE	H 25 18-S 37-E									
Type of Release Gas Volume of Release 106 MCF Volume Recovered 0 Source of Release RCF FLARE SSM EVENTS Was Immediate Notice Given? Yes No Not Required By Whom? NA Was a Watercourse Reached? Yes No Not Required If YES, To Whom? NA Date and Hour of Occurrence 8/17/2015 8:55:00 AM If YES, To Whom? NA Was a Watercourse Reached? Yes No Not Required If YES, Volume Impacting the Watercourse. NA If YES, Volume Impacting the Watercourse. NA Describe Cause of Problem and Remedial Action Taken.* Cause: FLARED AT NORTH HOBBS UNIT REINJECTION COMPRESSOR FACILITY (RCF). C TRAIN WENT DOWN DUE TO LOW OIL PRESSURE SHUT DOWN. Remedial Action Taken: OPERATIONS CHANGED FILTERS AND CHECKED THE AUXILIARY OIL SYSTEM. COMPRESSOR WAS RESTARTED AFTER CHECKS. Describe Area Affected and Cleanup Action Taken.* NONE										
Type of Release Gas Source of Release Source of Release Source of Release RCF FLARE SSM EVENTS Was Immediate Notice Given? Yes No Not Required By Whom? NA Was a Watercourse Reached? Yes No Not Required If YES, Volume Impacting the Watercourse. NA Describe Cause of Problem and Remedial Action Taken. PLARED AT NORTH HOBBS UNIT REINJECTION COMPRESSOR FACILITY (RCF). C TRAIN WENT DOWN DUE TO LOW OIL PRESSURE SHUT DOWN. Remedial Action Taken: OPERATIONS CHANGED FILTERS AND CHECKED THE AUXILIARY OIL SYSTEM. COMPRESSOR WAS RESTARTED AFTER CHECKS. Describe Area Affected and Cleanup Action Taken. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger.	Latitude <u>32°43'14.</u>	<u>.96''</u> Longitude <u>103</u>	3°11'59.65"							
Source of Release RCF FLARE SSM EVENTS Was Immediate Notice Given? Yes No Not Required If YES, To Whom? NA										
RCF FLARE SSM EVENTS Was Immediate Notice Given? Yes No Not Required Not Required If YES, To Whom? NA Date and Hour NA If YES, Volume Impacting the Watercourse. NA If a Watercourse was Impacted, Describe Fully. NA Describe Cause of Problem and Remedial Action Taken. Cause: FLARED AT NORTH HOBBS UNIT REINJECTION COMPRESSOR FACILITY (RCF). C TRAIN WENT DOWN DUE TO LOW OIL PRESSURE SHUT DOWN. Remedial Action Taken: OPERATIONS CHANGED FILTERS AND CHECKED THE AUXILIARY OIL SYSTEM. COMPRESSOR WAS RESTARTED AFTER CHECKS. Describe Area Affected and Cleanup Action Taken. NONE I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger										
Was Immediate Notice Given? Yes No Not Required If YES, To Whom? NA										
By Whom? NA Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. NA If a Watercourse was Impacted, Describe Fully. Describe Cause of Problem and Remedial Action Taken. Cause: FLARED AT NORTH HOBBS UNIT REINJECTION COMPRESSOR FACILITY (RCF). C TRAIN WENT DOWN DUE TO LOW OIL PRESSURE SHUT DOWN. Remedial Action Taken: OPERATIONS CHANGED FILTERS AND CHECKED THE AUXILIARY OIL SYSTEM. COMPRESSOR WAS RESTARTED AFTER CHECKS. Describe Area Affected and Cleanup Action Taken. NONE I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger.		If YES, To Who								
Was a Watercourse Reached? Yes No If a Watercourse was Impacted, Describe Fully. NA Describe Cause of Problem and Remedial Action Taken. Cause: FLARED AT NORTH HOBBS UNIT REINJECTION COMPRESSOR FACILITY (RCF). C TRAIN WENT DOWN DUE TO LOW OIL PRESSURE SHUT DOWN. Remedial Action Taken: OPERATIONS CHANGED FILTERS AND CHECKED THE AUXILIARY OIL SYSTEM. COMPRESSOR WAS RESTARTED AFTER CHECKS. Describe Area Affected and Cleanup Action Taken. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger.		i	d NA							
If a Watercourse was Impacted, Describe Fully. Describe Cause of Problem and Remedial Action Taken. Cause: FLARED AT NORTH HOBBS UNIT REINJECTION COMPRESSOR FACILITY (RCF). C TRAIN WENT DOWN DUE TO LOW OIL PRESSURE SHUT DOWN. Remedial Action Taken: OPERATIONS CHANGED FILTERS AND CHECKED THE AUXILIARY OIL SYSTEM. COMPRESSOR WAS RESTARTED AFTER CHECKS. Describe Area Affected and Cleanup Action Taken. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger.										
Describe Cause of Problem and Remedial Action Taken.* Cause: FLARED AT NORTH HOBBS UNIT REINJECTION COMPRESSOR FACILITY (RCF). C TRAIN WENT DOWN DUE TO LOW OIL PRESSURE SHUT DOWN. Remedial Action Taken: OPERATIONS CHANGED FILTERS AND CHECKED THE AUXILIARY OIL SYSTEM. COMPRESSOR WAS RESTARTED AFTER CHECKS. Describe Area Affected and Cleanup Action Taken.* NONE I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger										
Describe Cause of Problem and Remedial Action Taken.* Cause: FLARED AT NORTH HOBBS UNIT REINJECTION COMPRESSOR FACILITY (RCF). C TRAIN WENT DOWN DUE TO LOW OIL PRESSURE SHUT DOWN. Remedial Action Taken: OPERATIONS CHANGED FILTERS AND CHECKED THE AUXILIARY OIL SYSTEM. COMPRESSOR WAS RESTARTED AFTER CHECKS. Describe Area Affected and Cleanup Action Taken.* NONE I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger	If a Watercourse was Impacted Describe Fully 9	l l								
Cause: FLARED AT NORTH HOBBS UNIT REINJECTION COMPRESSOR FACILITY (RCF). C TRAIN WENT DOWN DUE TO LOW OIL PRESSURE SHUT DOWN. Remedial Action Taken: OPERATIONS CHANGED FILTERS AND CHECKED THE AUXILIARY OIL SYSTEM. COMPRESSOR WAS RESTARTED AFTER CHECKS. Describe Area Affected and Cleanup Action Taken. NONE I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger										
Cause: FLARED AT NORTH HOBBS UNIT REINJECTION COMPRESSOR FACILITY (RCF). C TRAIN WENT DOWN DUE TO LOW OIL PRESSURE SHUT DOWN. Remedial Action Taken: OPERATIONS CHANGED FILTERS AND CHECKED THE AUXILIARY OIL SYSTEM. COMPRESSOR WAS RESTARTED AFTER CHECKS. Describe Area Affected and Cleanup Action Taken. NONE I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger										
Cause: FLARED AT NORTH HOBBS UNIT REINJECTION COMPRESSOR FACILITY (RCF). C TRAIN WENT DOWN DUE TO LOW OIL PRESSURE SHUT DOWN. Remedial Action Taken: OPERATIONS CHANGED FILTERS AND CHECKED THE AUXILIARY OIL SYSTEM. COMPRESSOR WAS RESTARTED AFTER CHECKS. Describe Area Affected and Cleanup Action Taken. NONE I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger										
FLARED AT NORTH HOBBS UNIT REINJECTION COMPRESSOR FACILITY (RCF). C TRAIN WENT DOWN DUE TO LOW OIL PRESSURE SHUT DOWN. Remedial Action Taken: OPERATIONS CHANGED FILTERS AND CHECKED THE AUXILIARY OIL SYSTEM. COMPRESSOR WAS RESTARTED AFTER CHECKS. Describe Area Affected and Cleanup Action Taken. NONE I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger										
SHUT DOWN. Remedial Action Taken: OPERATIONS CHANGED FILTERS AND CHECKED THE AUXILIARY OIL SYSTEM. COMPRESSOR WAS RESTARTED AFTER CHECKS. Describe Area Affected and Cleanup Action Taken. NONE I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger		D DAGILITATION	27 PP 5 A P3 F 3 F 4 P5 S 100 S 100 S							
OPERATIONS CHANGED FILTERS AND CHECKED THE AUXILIARY OIL SYSTEM. COMPRESSOR WAS RESTARTED AFTER CHECKS. Describe Area Affected and Cleanup Action Taken.* NONE I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger	SHUT DOWN.	R PACILITY (RCF).	C TRAIN WENT	DOWN DUE	TO LOW	OIL PI	RESSURE			
Describe Area Affected and Cleanup Action Taken.* NONE I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger										
NONE I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger	Describe Area Affected and Cleanus Action Token	LIARY OIL SYSTEM.	. COMPRESSOR	WAS RESTA	ARTED AF	TER C	HECKS.			
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger										
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger										
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger										
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger	I hereby certify that the information given above is true and complete to	to the best of my know	vledge and understa	and that pursu	ant to NMC	CD ru	iles and			
	regulations all operators are required to report and/or file certain release	se notifications and per	rform corrective act	tions for relea	ases which r	nav en	danger			
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health	should their operations have failed to adequately investigate and comed	y the NMOCD marked	l as "Final Report" o	does not relic	ve the open	tor of	liability			
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other	or the environment. In addition, NMOCD acceptance of a C-141 repor	et does not relieve the	operator of respons	ground water, sibility for co	Surrace wat muliance wi	cr, nur th anv	nan nealth other			
federal, state, or local laws and/or regulations.	federal, state, or local laws and/or regulations.					ar any	VIII-6.			
OIL CONSERVATION DIVISION	000	0	OIL CONSERV	ATION I	DIVISIO	<u>N</u>				
Signature:	Signature:									
Approved by District Supervisor:		Approved by Distri	ict Supervisor:							
Printed Name: JOEY-RODGERS Approved by District Supervisor:	Printed Name: JOEY-RODGERS	13								
Title: HES OPS ADVISOR Approval Date: Expiration Date:	Title: HES OPS ADVISOR	Approval Date:		Expiration D	ate:					
E-mail Address: joey rodgers@oxy.com Conditions of Approval: Attached	E-mail Address: joey_rodgers@oxy.com	Conditions of Appr	roval:		Attnohad					
Date: 8/18/2015 Phone: (806)592-7311	Date: 8/18/2015 Phone: (806)592-7311				Attached	L				

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District III
100 Rio Brazos Road, Aztec, NM 87410
District III District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141

Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back side of form

						OPERA'	OR		Initi	al Report	\times	Final Rep		
		CCIDENTA		IAN LTD.		Contact JOE	Y RODGERS			, and a second	- tend			
		nolind Road,				Telephone No. (806)592-7311								
Facility Na	me NORT	H HOBBS U	NIT RC	F/WIB		Facility Typ	e OIL AND G	AS PRO	DUCTIO	N FACILI	TY			
Surface Ow	ner Occid	ental Permia	n LTD.	Mineral C)wner	HOBBS (G-S	A)	Lease No.						
				LOCA	TIO	N OF REI	EASE		145		- 335			
Unit Letter	Section	Township	Range	Feet from the		h/South Line	Feet from the	East/V	Vest Line	County				
Н	25	18-S	37-E							Lea				
	.1	<u> </u>		Latitude 32°43	2140	611 I maritud	103011150 65			<u> </u>				
						OF RELI		_						
Type of Rele	ase Gas			INAT	UKI		Release 67 MCF	: 1	Volume I	Recovered 0				
Source of Re	lease						our of Occurrence			Hour of Dis	מטפיי			
RCF FLARE SSM EVENTS Was Immediate Notice Given?						8/24/2015	10:40:00 PM			5 10:40:00 P				
was tmmedia	ale Notice (Ves I∇	No 🔲 Not Re	en sêco-l	IF YES, To	Whom?							
By Whom? N	JA	<u> </u>	163 🔼	140 T 1401 KG	quired									
Was a Water		:hed?				Date and H	our NA lume Impacting (tha 11/2-						
			Yes 🗵	No		NA NA	iume impacting i	ine wate	rcourse.					
If a Watercon	irse was Im	pacted, Descri	he Fully 3											
Cause: FLARED DU Remedial Act FIELD OPER	JE TO ENE tion Taken: RATIONS F		OMPRES	SOR SHUTTING		'N ON HIGH T	EMPERATURE							
public health should their o or the enviror	or the environs homent. In a	are required to conment. The ave failed to a	report an acceptanc dequately CD accep	is true and compl d/or file certain re e of a C-141 repo investigate and re tance of a C-141 r	lease i rt by th media	notifications anne NMOCD ma	d perform correct rked as "Final Roon that pose a three the operator of the	tive acti eport" de eat to gre responsil	ons for rele ces not rele ound water bility for c	eases which leve the oper r, surface wa ompliance w	may er ator of ter, hu ith any	idanger liability		
Signature: Printed Name: JOEY-RODGERS						Approved by 1	OIL CONS District Superviso		<u>ATION</u>	DIVISIO	<u>N</u>			
Title: HES O						Approval Date		E	xpiration	Date:				
E-mail Address: joey_rodgers@oxy.com						Conditions of Approval:			Attached [
Date: 08/2 Attach Addit	5/2015 ional Shee	ts If Necessa	rv	hone: (806)592-7	311					<u>L</u>				

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

					OPERATOR Initial Report Final Report							al Report		
Name of Co	mpany O	CCIDENTA	L PERM	IAN LTD.		Contact JOEY RODGERS								
		olind Road,					No. (806)592-73							
racinty Nai	ne NORT	H HOBBS L	INIT RC	F/WIB		Facility Typ	e OIL AND GA	AS PRO	DUCTIO	N FACILI	ΓΥ			
Surface Ow	ner Occid	ental Permia	n LTD.	Mineral O	wner I	er HOBBS (G-SA) Lease No.								
				LOCA	TIO	ON OF RELEASE								
Unit Letter	Section	Township	Range	Land Control of the C		/South Line	Feet from the	Enst/W	est Line	County				
Н	25	18-S	37-E							Lea				
				Latitude 32°43'	14.96	" Longitud	e 103°11'59.65'	1						
	NATURE OF RELEASE													
Type of Rele						Volume of Release 1462.99 MCF Volume Recovered 0								
Source of Re		NTC				Date and Hour of Occurrence Date and Hour of Discovery								
Was Immedia						8/25/2015 5:18:00 AM 8/25/2015 5:18:00 AM								
			Yes 🗵	No Not Req	quired	If YES, To Whom? NA								
By Whom? N Was a Watero		L - In				Date and Hour NA								
was a water	ourse Keac	nea?	Yes 🗵	No		If YES, Volume Impacting the Watercourse.								
IC- Watana		_				IAM								
If a Watercou	rse was im	oacted, Descri	be Fully."											
Describe Cau	Describe Cause of Problem and Remedial Action Taken.*													
Cause:														
INTERMITT	ENT FLAR	ING AT NO	RTH HOE	BS UNIT REINJE	ECTIO	N COMPRES	SOR FACILITY	(RCF).	C TRAIN	WAS TAK	EN DO	WN I	FOR	
MAKE NEW	TIE INS.	D LICATIO I V	KEN DU	WN FOR AN ANN	NUAL	PM. ALSO I	DEPRESSURED	INLET A	AND DISC	CHARGE HI	EADER	RS TO)	
Remedial Act														
INLET RATE	S FROM T	HE FIELD W	ERE REI	DUCED TO HELP	MINI	MIZE THE F	LARE. FLARIN	G CEAS	ED ONC	THE INLE	T ANI)		
DISCHARGE Describe Area	HEADEK	2 MEKE DEI	KESSUR	ED.										
NONE	, refrected b	ara Cicanab V	etion rak	cn. ·										
													İ	
I hereby certif	y that the in	oformation give	en above	is true and comple	te to th	ne hest of my	knowledge and ur	derstan	that nure	unnt to NIMC	איייי פון	100.00		
i i cigutations an	ODCIMIO12 F	re reamirea to	i iedoni an	O/OF THE CERTAIN FEL	መደም ከ ሰ	Attications or	d poetoess comment	liera aadim		and a second state of				
f bright negiting	or une envir	onment. The	acceptance	e of a C-141 renort	t hv the	: NMOCD mi	arked as "Final De	north do	ne not esti-	aug the ones	1 - m - f	10-1-01	ten [
Supring micht of	heranions in	ive imited to m	ucquatciy	investigate and ren ance of a C-141 re	nediale	e conforminatio	in that make a thre	of to are	und water	cuefoca umi	an Line	1	and bloom	
federal, state,	or local law	s and/or regu	lations.	micc of a C-141 (C	port ut	nes not tellest	tile operator of re	esponsio	HIIY IOF CO	impliance w	th any	other		
						OIL CONS	SERVA	ATION	DIVISIO	N				
Signature:	X	X_/							-					
		0/		Amazza de filos	D11									
Printed Name: JOEY RODGERS						Approved by	District Superviso	or:						
Title: HES OI	S ADVISO	OR				Approval Date	**	E	xpiration I	Date:				
E-mail Addres	s: inev_rod	oers@avu co	m			Cdisi C								
	100	ды энулду.со:	H1		'	Conditions of	Approval:		Attached					
	6/2015		Phone: (306)592-7311										
Attach Additi	anal Chaoi	c If Macana	975.7											

District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

			··- <u>.</u>			-, - 1112 0 7 0	00										
			Rel	ease Notific	atio	n and Co	rrective A	ction									
						OPERATOR Initial Report											
		CCIDENTA		IAN LTD.		Contact JOI	Y RODGERS					Final Report					
Address 10	17 W. Star	rolind Road,	Hobbs			Telephone 1	No. (806)592-73	311									
Facility Nar	ne NORT	H HOBBS U	NIT RC	F/WIB					DUCTIO	N FACILI	TV						
Surface Ow	ner Occide	ental Permia	LTD	Minoral		Facility Type OIL AND GAS PRODUCTION FACILITY oer HOBBS (G-SA) Lease No.											
Barrace OW	ner Occid	cital i cilila	ILLID.														
	I =	I				ON OF RELEASE											
Unit Letter	Section	Township	Range	Feet from the	North	South Line	Feet from the	East/W	st Line	County							
Н	25	18-S	37-E							Lea							
	1	L			L												
				Latitude 32°43	3'14.96	" Longitud	e 103°11'59.65'	H									
Latitude <u>32°43'14.96"</u> Longitude <u>103°11'59.65"</u> NATURE OF RELEASE																	
Type of Relea	ose Gas			NAT	URE												
Source of Re					Release 238 MC lour of Occurrence			Recovered 0									
RCF FLARE		NTS			iour of Occurrenc 8:16:00 AM			Hour of Dis									
Was Immedia				***************************************		If YES, To		1	5/2//2013	5 8:16:00 A	М						
			Yes 🗵	No 🔲 Not Re	quired	NA	M HOUR										
By Whom? N	ÍΑ					Date and H	our NA										
Was a Watero	ourse Read	hed?						he Water	'Augea								
			Yes 🗵	No		If YES, Volume Impacting the Watercourse. NA											
If a Watergow	rce weet Im-	and Daniel	h. P. II. 1														
If a Watercourse was Impacted, Describe Fully.* NA																	
Describe Cause of Problem and Remedial Action Taken.* Cause: INTERMITTENT FLARING AT NORTH HOBBS UNIT REINJECTION COMPRESSOR FACILITY (RCF). A TRAIN SHUT DOWN DUE TO LOW LUBE FLOW. Remedial Action Taken: MAINTENANCE CHANGED OUT THE PRO FLOW AND OPERATIONS RESTARTED THE COMPRESSOR												JE TO LOW					
I hereby certif	Describe Area Affected and Cleanup Action Taken.* NONE I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and																
public health should their o	operators: or the envir perations had ment. In a	are required to conment. The ave failed to a ddition, NMO	report an acceptanc dequately CD accep	d/or file certain re e of a C-141 repo investigate and re tance of a C-141	clease no rt by the emediate	otifications ar NMOCD ma contamination	id perform correct trked as "Fing! Ro on that nose a thre	tive action eport" doc eat to goo	ns for rele s not reli	eases which eve the ope	may er	danger liability					
Signature:	X					Approved by	OIL CONS		TION	DIVISIO	<u>N</u>						
Printed Name	: JOEY KU	DOPRA		<u> </u>			,	1									
Title: HES O	PS ADVIS	OR				Approval Date	5 :	Ex	piration l	Date:							
E-mail Addres	ss: joey roc	lgcrs@oxy.co	m			Approval Date: Expiration Date: Conditions of Approval: Attached											

Phone: (806)592-7311

Date: 08/28/2015

^{*} Attach Additional Sheets If Necessary

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

	OPERATOR Initial Report Fi								
Name of Company OCCIDENTAL PERMIAN LTD.	Contact JOEY RODGERS								
Address 1017 W. Stanolind Road, Hobbs	Telephone No. (806)592-7311								
Facility Name NORTH HOBBS UNIT RCF/WIB	Facility Type OIL AND GAS		N FACILITY						
Surface Owner Occidental Permian LTD. Mineral Owner	HODDO (C. C.)	Lease N							
Surface Owner Occidental Fertilian LTD. Mineral Owner	HOBBS (G-SA)	0.							
LOCATIO	ON OF RELEASE								
	th/South Line Feet from the	East/West Line	County						
H 25 18-S 37-E			Lea						
Latitude 32°43'14.9	<u> </u>								
NATUR	E OF RELEASE								
Type of Release Gas Source of Release	Volume of Release 236.99 MCF Volume Recovered 0								
RCF FLARE SSM EVENTS	Date and Hour of Occurrence Page 2015 12:25:00 PM								
Was Immediate Notice Given?	8/28/2015 12:35:00 PM								
☐ Yes ☒ No ☐ Not Require	d NA								
By Whom? NA	Date and Hour NA								
Was a Watercourse Reached?	If YES, Volume Impacting th	e Watercourse.							
☐ Yes ☒ No	NA								
If a Watercourse was Impacted, Describe Fully.*									
NA									
Describe Cause of Problem and Remedial Action Taken.*									
Cause:									
INTERMITTENT FLARING AT NORTH HOBBS UNIT REINJECTION	ON COMPRESSOR FACILITY (RCF). C TRAIN :	SHUT DOWN TO CHANGE						
OUT HOT VALVES. B TRAIN SHUT DOWN DUE TO LOSS OF IN	ILET RATE FROM THE FIELD I	DURING STORM	ı.						
Remedial Action Taken:									
MAINTENANCE CHANGED OUT HOT VALVES ON C TRAIN AN AFTER INLET RATE FROM FIELD RETURNED TO NORMAL.	D OPERATIONS RESTARTED	COMPRESSOR.	B TRAIN WAS STARTED						
Describe Area Affected and Cleanup Action Taken.*									
NONE									
I hambu conife that the information is a little of the state of the st									
I hereby certify that the information given above is true and complete to	the best of my knowledge and un	derstand that pursu	Jant to NMOCD rules and						
regulations all operators are required to report and/or file certain release public health or the environment. The acceptance of a C-141 report by t	he MACCD marked as "Fire! Be-	ive actions for rele	ases which may endanger						
should their operations have failed to adequately investigate and remedi	ate contamination that nose a three	pore does not relie	surface water burns bealth						
or the environment. In addition, NMOCD acceptance of a C-141 report	does not relieve the operator of re	snonsibility for co	mnliance with any other						
federal, state, or local laws and/or regulations.		-point, 101 co	inpinance with any outer						
	OIL CONS	ERVATION	DIVISION						
Signatura									
Signature:									
Printed Name: JOEY RODGERS	Approved by District Supervisor	ri .							
Title: HES OPS ADVISOR	Approval Date:	Expiration D	Date:						
E-mail Address: joey rodgers@oxy.com	Conditions of Approvals								
	Conditions of Aphtovait	Conditions of Approval:							
Date: 08/31/2015 Phone: (806)592-7311									
Attach Additional Sheets If Necessary									

District I 1625 N. French Dr., Hobbs, NM 88240 District III

1301 W. Grand Avenue, Artesia, NM 88210

District IIII 1000 Rio Brazos Road, Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

			OPERA	ΓOR		☐ Initial Report ☐ Final Report								
		CCIDENTA		IAN LTD.			NY AGUILAR							
		olind Road,					No. (575)397-82							
Facility Nar	ne NORTI	H HORRS C	INIT RC	F/WIB		Facility Typ	e OIL AND GA	AS PRO	RODUCTION FACILITY					
Surface Ow	ner Occide	ental Permia	n LTD.	Mineral C	wner I	HOBBS (G-S	SA)		Lease No.					
				LOCA	TIO	N OF REI	LEASE							
Unit Letter	Section	Township	Range	Feet from the	North	South Line	Feet from the	East/V	Vest Line	County				
H	25	18-S	37- E						Lea					
				Latitude <u>32°43</u>	3'14.96	<u>"</u> Longitude	e <u>103°11'59.65'</u>	··		<u> </u>				
				NAT	URE	OF RELI	EASE							
Type of Rele							Release 169 MC			Recovered 0				
Source of Re		NITC				1	lour of Occurrence	Hour of Dis	covery					
Was Immedia						9/2/2015 7:48:00 PM 9/2/2015 7:48:00 PM								
			Yes 🗵	No 🗌 Not Re	quired	If YES, To Whom? NA								
By Whom? N	IA		_			Date and Hour NA								
Was a Water	course Read		v N	Lxi			lume Impacting t	he Wate	rcourse.					
If a Watercou			Yes 🗵			NA NA								
Cause: FLARED IN' TO HIGH DI Remedial Act FIELD TECH GAS INTAK Describe Area	Describe Cause of Problem and Remedial Action Taken.* Cause: FLARED INTERMITTENLY AT THE NORTH HOBBS UNIT REINJECTION COMPRESSOR FACILITY (RCF). LP COMPRESSOR DOWN DUE TO HIGH DISCHARGE TEMPERATURE SHUTDOWN. C-TRAIN DOWN DUE TO HIGH OIL TEMP SHUTDOWN. EOR Remedial Action Taken: FIELD TECH ADDED OIL TO OIL SEPERATOR AND THE LP COMPRESSOR WAS RESTARTED AND RUNNING. THE FIELD CUT BACK ON GAS INTAKE TO PLANT TO STOP FLARING, C-TRAIN WAITING TO REPLACE BAD TRANSMITTER. Describe Area Affected and Cleanup Action Taken.* ALL GAS BURNED AT FLARE.											BACK ON		
regulations al public health should their o	I operators or the envir perations hament. In a	are required to conment. The ave failed to a ddition, NMO	report an acceptance dequately CD accep	d/or file certain re e of a C-141 repo investigate and re tance of a C-141 r	elease no rt by the emediate	otifications and NMOCD made contamination	d perform correcarked as "Final Report that pose a three	tive action of the control of the co	ons for rele oes not reli	eases which eve the oper	may en ator of	danger liability		
							OIL CONS	SERV	ATION	DIVISIO	N			
Signature:	Jones	1 Secu)											
Printed Name	: TONY A	GUILAR		/	Approved by District Supervisor:									
Title: 748	55	recial	ast			Approval Date	oval Date: Expiration			Date:				
E-mail Addre	ss: RAYM(OND_AGUIL	AR@OX	Y.COM		Conditions of Approval:				Attests				
Date: 9 -				(575)397-8251						Attached	П			
Attach Addit	ional Shee	ts If Necessa	ary											

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 2 Copies to appropriate District Office in accordance

with Rule 116 on back side of form

Form C-141 Revised October 10, 2003

					OPERATOR ☐ Initial Report ☒						Final Report			
Name of Co				IAN LTD.		Contact TONY AGUILAR								
		olind Road,					No. (575)397-82							
Facility Nar	ne NORT	H HOBBS L	NIT RC	F/WIB	l	Facility Type OIL AND GAS PRODUCTION FACILITY								
Surface Ow	ner Occide	ental Permia	n LTD.	Mineral C	wner H	IOBBS (G-S								
				LOCA	TION	ION OF RELEASE								
Unit Letter	Section	Township	Range	Feet from the		South Line	Feet from the	East/\	West Line	County				
H	25	18-S	37-E							Lea				
				Latitude 32°43	3'14.96'	Longitud	e <u>103°11'59.65'</u>	1		<u> </u>				
				NAT	URE	OF RELI	EASE							
Type of Release						Volume of Release 137 MCF Volume Recovered 0								
Source of Rel		NTS				Date and H 9/3/2015 3	lour of Occurrenc	е		Hour of Disc 3:58:00 PM	covery			
Was Immedia						If YES, To			7/3/2013	3.36.001141				
			Yes 🗵	No Not Re	equired	NA								
By Whom? N						Date and Hour NA								
Was a Watero	course Read	thed?] No		If YES, Volume Impacting the Watercourse. NA									
If a Watercourse was Impacted, Describe Fully.*														
NA														
Describe Cau	se of Proble	em and Reme	dial Action	n Taken.*					_					
Cause:														
FLARED AT SHUTDOWN		TH HOBBS	UNIT REI	NJECTION COM	1PRESS	OR FACILIT	TY (RCF). C-TRA	VIN DO	WN DUE 1	ro high o	IL TEN	МР		
Remedial Act														
				AIN AND FLAR	ING ST	OPPED.								
Describe Area			Action Tak	en.*										
I TIED ON D	JKI 100 111	TEMES.												
I hereby certif	fy that the i	nformation gi	ven above	is true and comp	lete to th	e best of my	knowledge and u	nderstai	nd that purs	uant to NM0	OCD n	ules and		
regulations al	l operators	are required to	o report ar	nd/or file certain r	elease no	otifications ar	nd perform correc	tive act:	ions for rele	eases which	may er	ndanger		
public health	or the envir	onment. The	acceptano	te of a C-141 repo	ort by the	NMOCD ma	arked as "Final Re on that pose a thre	eport" d	loes not reli	eve the oper	ator of	liability		
or the environ	ment. In a	ddition, NMC	CD accep	tance of a C-141	report do	es not reliev	e the operator of t	esponsi	ibility for co	, surrace wa ompliance w	ith any	man neamn v other		
federal, state,					·					·				
	1		11			OIL CONSERVATION DIVISION								
Signature:	Ine	Lou	law											
Printed Name	: TONV A	GUILAR		A	Approved by District Supervisor:									
Title: 748	5 Su	recial	at		F	Approval Dat	e: Expiration Da			Date:	Pate:			
E-mail Addre	ss: RAYM	OND_AGUIL	AR@OX	Y.COM	(Conditions of	Approval:			Attached				
Date: 9-4	4-15		Phone:	(575)397-8251										

^{*} Attach Additional Sheets If Necessary