

From: [Yu, Olivia, EMNRD](#)
To: ["Pope, Gregory"; Martin, Ed; "Mann, Ryan"](#)
Cc: [Strang, Dana V.; Naranjo, Mark](#)
Subject: RE: 1RP-4593
Date: Wednesday, April 4, 2018 3:55:00 PM
Attachments: approved_1RP 4593_EVGSAU 2923-001_Work Plan_REV1.pdf
image001.png
image003.png

Mr. Pope:

Please be advised that all scaled maps must include the release point, in relation to delineation sample locations.

NMOCD approves of the delineation completed and proposed remediation for 1RP-4593 with these conditions:

1. Confirmation sidewall samples for the proposed excavation of the area represented by SB-4.
2. If proposed depth of excavation is anticipated to not be obtainable, NMOCD and NMSLO must be informed for a site evaluation. At a minimum, photo documentation will be required.

Please confirm or inform for clarification.

Thanks,

Olivia Yu
Environmental Specialist
NMOCD, District I
Olivia.yu@state.nm.us
575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Pope, Gregory <Greg.Pope@tetrattech.com>
Sent: Monday, March 12, 2018 10:27 AM
To: Martin, Ed <emartin@slo.state.nm.us>; Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>
Cc: Strang, Dana V. <dvstrang@slo.state.nm.us>; Naranjo, Mark <MNaranjo@slo.state.nm.us>
Subject: RE: 1RP-4593

Mr. Martin & Ms. Yu,

Please find the attached Work Plan for the ConocoPhillips 1RP 4593-EVGSAU 2923-001 site, revised to include a revegetation plan. This revised document is being submitted for your review and approval, if in agreement, so Tetra Tech may proceed with the described remedial action. Please call

me or reply to this email with any questions or comments. Thank you.

Greg W. Pope, P.G. | Senior Project Manager / Geologist
Direct Office: 432.687.8134 | Cell: 432.661.3852 | Fax : 432.682.3946
greg.pope@tetrattech.com

Tetra Tech OGA | Complex World, Clear Solutions™
4000 N. Big Spring St., Suite 401 | Midland, TX 79705 | www.tetrattech.com

PLEASE NOTE: This message, including any attachments, may include privileged, confidential and/or inside information. Any distribution or use of this communication by anyone other than the intended recipient is strictly prohibited and may be unlawful. If you are not the intended recipient, please notify the sender by replying to this message and then delete it from your system.

From: Martin, Ed [<mailto:emartin@slo.state.nm.us>]
Sent: Tuesday, February 27, 2018 3:22 PM
To: Pope, Gregory <Greg.Pope@tetrattech.com>
Cc: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>; Strang, Dana V. <dvstrang@slo.state.nm.us>;
Naranjo, Mark <MNaranjo@slo.state.nm.us>
Subject: 1RP-4202, 1RP-4233, and 1RP-4593

The New Mexico State Land Office has reviewed the 3 work plans shown above and the remediation plans included therein are acceptable as far as they go. Re-seeding requirements on state lands were not included in the plans. Therefore, I am attaching NMSLO policy regarding that subject. Please include these requirements in the plans referred to, and in any future work plans you submit that concern state trust lands. For the time being, I am your NMSLO contact for these remediation plans.

Thank you and contact me if you have questions.

Ed Martin
Acting Assistant Commissioner
Oil Gas and Minerals Division
505.827.5746
New Mexico State Land Office
310 Old Santa Fe Trail
P.O. Box 1148
Santa Fe, NM 87504-1148
emartin@slo.state.nm.us

.....
CONFIDENTIALITY NOTICE: This e-mail, including all attachments is for the sole use of the intended recipient[s] and may contain confidential and/or privileged information. Any unauthorized review, use, copying, disclosure or distribution is prohibited, unless specifically provided under the New Mexico Inspection of Public Records Act. If you are not the intended recipient, please contact the sender at once and destroy all copies of this message.

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>
