



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

Susana Martinez
Governor

John H. Bemis
Cabinet Secretary

Jami Bailey
Division Director
Oil Conservation Division

Response Required – Deadline Enclosed

*Field Inspection Program
"Preserving the Integrity of Our Environment"*

12-Oct-11

HOBBS OCD

ENDEAVOR ENERGY RESOURCES, LP
110 NORTH MARIENFELD SUITE 200
MIDLAND TX 79701

OCT 13 2011

RECEIVED

LETTER OF VIOLATION - Inspection

Dear Operator,

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

LEVICK STATE No.002				G-20-8S-33E	30-005-10123-00-00		
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.	
10/12/2011	Plugged Well Surface Restor	Maxey Brown	Yes	No	1/15/2012	iMGB1128553024	
Comments on Inspection:		DO NOT RELEASEE RULE 19 15 25 10 LARGE PILE OF CALACHI NORTH OF WELL NEEDS TO BE LEVELLED TO NATURE CONTOUR THIS IS 1ST LETTER OF NON-COMPLIANCE MGB					
CONOCO No.003				N-15-8S-33E	30-005-20844-00-00		
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.	
10/12/2011	Plugged Well Surface Restor	Maxey Brown	Yes	No	1/15/2012	iMGB1128553539	
Comments on Inspection:		DO NOT RELEASEE RULE 19 15 25 10 NEED TO REMOVE ELECTRICAL MAIN DISCONNECT AND METER BASE WITH CONDUIT RISER FROM POLE THIS IS 1ST LETTER OF NON-COMPLIANCE REMINDER TO CONTACT LEA COUNTY ELEC COOP IF SECONDARY POLES WILL NOT BE USED IN FUTURE OPERATIONS MGB.					

OCT 13 2011

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,



COMPLIANCE OFFICER

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data
*Significant Non-Compliance events are reported directly to the EPA Region VI, Dallas, Texas

NEED TO LEVEL
PILE OF CALACHI



LOW AREA


10/12/2011

FNDEAVOR

LEVICK STATE #2

30-005-10123

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



HASLER	015H14150977	US POSTAGE
	\$0.44	
	10/12/11	
	Mailed From 88240	

ENDEAVOR ENERGY RESOURCES, LP
110 NORTH MARIENFELD SUITE 200
MIDLAND TX 79701