

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
October 13, 2009

HOBBS OCD

OIL CONSERVATION DIVISION

FEB 17 2012

1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-28683
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator LINN OPERATING, INC.		6. State Oil & Gas Lease No.
3. Address of Operator 600 TRAVIS, SUITE 5100, HOUSTON, TEXAS 77002		7. Lease Name or Unit Agreement Name SEVEN RIVERS QUEEN UNIT
4. Well Location Unit Letter <u>K</u> ; <u>1555</u> feet from the <u>S</u> line and <u>2480</u> feet from the <u>W</u> line Section <u>34</u> Township <u>22S</u> Range <u>36E</u> NMPM LEA County		8. Well Number: <u>062</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number <u>269324</u>
		10. Pool name or Wildcat EUNICE;SEVEN RIVERS-QUEEN, SOUTH

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

2/2/2012 - MIRUPU, dig out WH NUBOP.

2/3/2012 - TIH w/ tbg, tag existing cmt on CIBP @ 3571'. Circ hole w/ mud. POH to 2800', break circ, spot 25 sxs cmt disp TOC to 2560', POH w/ tbg, std back 19 stds. LD rest of tbg. Received approval from Mark Whitaker w/ OCD for the P&A operation.

2/6/2012 - TIH w/ 4-3/4 bit & 5-1/2" csg scraper to 1241', POH w/ scraper & bit. As per OCD, RIH w/ WL perf @ 1300' w/ 4 shots. RD WL. TIH w/ 5-1/2" pkr to 915' load hole. Set pkr. Unable to pump into perfs. Held 1000 psi. OCD ok to sot cmt. POH w/ tbg & pkr. TIH w/ tbg to 1350', break circ. Spot 25 sxs cmt w/ 2% Cal. Disp TOC to 1110'. POH, LD tbg. WOC. RIH w/ tbg, tag cmt @ 1090', OCD ok w/ tag. POH w/ tbg. RIH w/ WL, perf 383' w/ 4 sqz holes. POH WL. RIH w/ pkr & 1 jt tbg. Set pkr. Could not pump into. Held 800 psi. Called OCD. POH tbg & pkr, perf @ 60'. TIH w/ tbg to 433', break circ, spot 40 sxs cmt, POH, tbg, NDBOP RIH w/ pkr & 1 jt tbg. Set pkr, circ 20 sxs cmt to surface. Rlse pkr, fill 5-1/2" csg w/ cmt. POH.

2/7/2012 - Cut off & remove well head, install P&A Marker, RDPU. Cut off anchors below ground level. Clean location.

Spud Date:

Rig Release Date:

Approved for plugging of well bore only.
Liability under bond is retained pending receipt
of C-103 (Subsequent Report of Well Plugging)
which may be found at OCD Web Page under
Forms. www.enr.state.nm.us/oed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE: REGULATORY SPECIALIST III DATE FEBRUARY 15, 2012

Type or print name TERRY B. CALLAHAN E-mail address: tcallahan@linenergy.com PHONE: 281-840-4272

For State Use Only

APPROVED BY:

TITLE

DATE

Conditions of Approval (if any):

FEB 21 2012