

Submit 1 Copy To Appropriate District Office
 District I - (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II - (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III - (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV - (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised August 1, 2011

HOBBS OGD CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

AUG 15 2012

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		WELL API NO. 30-025-28575 ✓
2. Name of Operator OXY USA WTP Limited Partnership ✓		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
3. Address of Operator P.O. Box 50250 Midland, TX 79710		6. State Oil & Gas Lease No. LG 1543
4. Well Location Unit Letter <u>J</u> : <u>1980</u> feet from the <u>south</u> line and <u>1650</u> feet from the <u>east</u> line Section <u>12</u> Township <u>18S</u> Range <u>33E</u> NMPM County <u>Lea</u>		7. Lease Name or Unit Agreement Name State DW ✓
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4097' GR		8. Well Number <u>1</u> ✓ 9. OGRID Number <u>192463</u> ✓ 10. Pool name or Wildcat Mesquero Escarpe Bone Springs ✓

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPL <input type="checkbox"/> DOWNHOLE COMMINGLE <input type="checkbox"/>		SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input checked="" type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See Attached

Approved for plugging of well bore only.
 Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OGD Web Page under Forms, www.emnrd.state.nm.us/ogd.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Stewart TITLE Regulatory Advisor DATE 8/13/12

Type or print name David Stewart E-mail address: david_stewart@oxy.com PHONE: 432-685-5717

APPROVED BY: [Signature] TITLE Dist. Mgr DATE 8-16-2012

Conditions of Approval (if any):

AUG 16 2012

State DW #1

- 7/31/12 MIRU PU, NDWH, NU BOP
- 8/1/12 RIH w/ pkr & set @ 6107'
- 8/2/02 Open bypass, circ hole w/ FW, close bypass, blow popoout plug @ 2100#, pump FW @ 2BPM @ 500#.
- 8/3/12 NU stripper to BOP, pump FW @ 3.5BPM @ 800#, sqz 400sx CL H cmt, pump 18bbl flush, cmt louted up @ 2000#, open bypass, rev out 82sx cmt, rel pkr, POOH.
- 8/6/12 RIH.w/ tbg & tag cmt @ 6107', circ hole w/ 10# MLF, POOH. RIH w/ pkr & set @ 5538', RIH w/ WL & perf @ 5938', RDWL. Pressure perms to 1000# w/ no loss, rel pkr & POOH.
- 8/7/12 RIH w/ tbg to 5981', spot 25sx CL C cmt, POOH, WOC. RIH w/ WL & tag cmt @ 5698', PUH & perf @ 5333', POOH w/ WL. RIH w/ pkr & set @ 4874', pressure perms to 1000# w/ no loss, POOH. RIH to 5380', spot 35sx CL C cmt, POOH, WOC.
- 8/8/12 RIH & tag cmt @ 5050', PUH & perf @ 4428', POOH. RIH w/ WL, run CBL from 4600-1000', no cement. RIH & perf @ 4428', POOH w/ WL. RIH w/ pkr & set @ 4050', EIR @ 2BPM w/ full returns, sqz 50sx CL C cmt, WOC.
- 8/9/12 Rel pkr, POOH. RIH w/ WL & tag cmt @ 4210'. PUH & perf @ 3253', POOH. RIH w/ pkr & set @ 2848', EIR @ 2BPM w/ full returns, sqz 50sx CL C w/ 2% CaCl₂, POOH, WOC. RIH & tag cmt @ 3044', PUH & perf @ 1819', POOH. RIH w/ pkr & set @ 1424', EIR @ 2BPM w/ full returns, sqz 50sx Cl C w/ 2% CaCl₂, WOC.
- 8/10/12 Rel pkr, POOH. RIH w/ WL & tag cmt @ 1565', PUH & perf @ 550', POOH. RIH w/ pkr & set @ 30', EIR @ 2BPM w/ full returns, circ 200sx Cl C cmt to surf. Rel pkr, NDBOP, top off csg, RDPU.