Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Hobbs

FORM APPROVED

	Expires		
ace Seri	al No	 	_

NMNM106715

SUNDRY NOTICES AND REPORTS ON WELLS	HOBBS O
Do not use this form for proposals to drill or to re-enter an	A COOCA
abandoned well. Use form 3160-3 (APD) for such proposals.	

6.	If Indian,	Αl	lottee or	Tribe	Name

•	DEC 1 0-000	· .
SUBMIT IN TRIPLICATE - Other inst	7. If Unit or CA/Agreement, Name and/or No. NMNM101361X	
1. Type of Well ☐ Gas Well ☐ Other	RECEIVED	8. Well Name and No. ESDU 007
	t: VICKIE MARTINEZ FINEZ@SM-ENERGY.COM	9. API Well No. 30-025-29887
3a. Address 3300 N "A" STREET BLDG 7-200 MIDLAND, TX 79705	3b. Phone No. (include area code) Ph: 432-688-1709 Fx: 432-688-1701	10. Field and Pool, or Exploratory SHUGART;DELAWARE,EAST
4. Location of Well (Footage, Sec., T., R., M., or Survey Descrip	otion)	11. County or Parish, and State
Sec 19 T18S R32E 760FNL 330FWL		LEA COUNTY, NM
12. CHECK APPROPRIATE BOX(ES)	TO INDICATE NATURE OF NOTICE, RI	EPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
Notice of Intent ☐ Subsequent Report ☐ Final Abandonment Notice	☐ Acidize ☐ Alter Casing ☑ Casing Repair ☐ Change Plans ☐ Convert to Injection	☐ Deepen ☐ Fracture Treat ☐ New Construction ☐ Plug and Abandon ☐ Plug Back	☐ Production (Start/Resume) ☐ Reclamation ☐ Recomplete ☐ Temporarily Abandon ☐ Water Disposal	☐ Water Shut-Off ☐ Well Integrity ☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

ISOLATE WELL. REMOVE PUMPING UNIT TO REPAIR SURFACE CASING. ONCE AREA IS CLEAR, WE WILL DIG AROUND THE WELLHEAD UNTIL WE REACH USEABLE PIPE. AT THAT POINT, WE WILL CUT OFF CORRODED PIPE AND WILL RE-WELD NEW SURFACE CASING AND WELLHEAD INTO PLACE AND PUT WELL BACK ON PRODUCTION.

SUBJECT TO LIKE APPROVAL BY STATE

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

SEE ATTACHED FOR CONDITIONS OF APPROVAL

<u> </u>		<u> </u>	
14. I hereby certify th	For SM ENERO	480 verified by the BLM Well Information GY COMPANY, sent to the Carlsbad processing by KURT SIMMONS on 10/25/2	•
Name (Printed/Typ	ed) VICKIE MARTINEZ	Title ENGINEER TECH II	
Signature	(Electronic Submission) THIS SPACE FOR	Date 10/25/2012 FEDERAL OR STATE OFFICE US	E APPROVED
Approved By		Title	DFC 5 2012
certify that the applicant	if any, are attached. Approval of this notice does not holds legal or equitable title to those rights in the su applicant to conduct operations berson.		BLOZEAU OF LAND MANAGEMENT
Title 18 U.S.C. Section	1001 and Title 43 U.S.C. Section 1212, make it a cri	me for any person knowingly and willfully to ma	

Conditions of Approval

SM Energy Company ESDU - 007 API 30-025-29887 T18S-R32E, Sec 19 December 05, 2012

- 1. Due to being within the Lesser Prairie Chicken habitat, this workover activity will be restricted to the hours of 9:00am through 3:00am for the period of March 1 through June 15. Exceptions to these restrictions may be granted by BLM's Johnny Chopp <jchopp@blm.gov> 575.234.2227 or Bob Ballard

 ballard@blm.gov> 575.234.5973.
- 2. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 3. Subject to like approval by the New Mexico Oil Conservation Division.
- 4. Class H > 7,500' & Class C < 7,500') cement to be used as needed. For any plug that requires a tag or pressure test a minimum WOC time of 4 hours (C) & 8 hours (H) is recommended. Formation isolation plugs of Class "C" to be mixed 14.8#/gal, 1.32 ft³/sx, 6.3gal/sx water and "H" to be mixed 15.6#/gal, 1.18ft³/sx, 5.2gal/sx water.
- 5. Surface disturbance beyond the originally approved disturbance shall have prior approval.
- 6. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 7. Functional H₂S monitoring equipment shall be on location.
- 8. A minimum 2,000 (2M) BOPE to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 (attachment 1, 2M diagrams of choke manifold equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 9. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.

- 10. Provide BLM with an electronic copy (Adobe Acrobat Document) cement bond log record from 5,100' or below to top of cement. The CBL may be attached to an email to pswartz@blm.gov
- 11. At least 24 hours before the casing integrity test contact: Andy Cortez acortez@blm.gov, (phone 575-393-3612 or 575-631-5801). If no answer, leave a voice mail with the API#, workover purpose, and a call back phone number. Note the contact notification method, time, & date in your subsequent report.
- 12. A BLM PET witnessed (charted) casing integrity test of 700 psig is required. Pressure leakoff may require remedial action before continuing with the proposed work. Include a copy of the chart in the subsequent sundry for this workover.

The subsequent sundry shall also include a detailed statement showing the location of any leaks found. Documentation of any cement placed shall also be detailed in the subsequent sundry.

- 13. Workover approval is good for 90 days (completion to be within 90 days of approval). A legitimate request is necessary for extension of that date.
- 14. File intermediate **subsequent report sundry** Form 3160-5 within 30 days of any interrupted workover procedures and a complete workover subsequent sundry.

JAM/PRS 120512

Access information for use of Form 3160-5 "Sundry Notices and Reports on Wells"

NM Fed Regs & Forms - http://www.blm.gov/nm/st/en/prog/energy/oil and gas.html

§ 43 CFR 3162.3-2 Subsequent Well Operations.

§ 43 CFR 3160.0-9 (c)(1) Information collection.

§ 3162.4-1 (c) Well records and reports.