HOBBS OCD

OCD Hobbs

Form 3160-5 (March 2012)

UNITED STATES DEC 2 4 2012 DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014

5. Lease Serial No. NMNM111963

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				INIMININI 1 1903		
				6. If Indian, Allottee or Tribe Name .		
SUBMIT IN TRIPLICATE – Other instructions on page 2.				7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well	· · · · · · · · · · · · · · · · · · ·					
☑ Oil Well ☐ Gas Well ☐ Other				8. Well Name and No. South Lusk 28 Federal #1 (308901)		
2. Name of Operator Apache Corporation (873)				9. API Well No. 30-025-36992		
3a. Address 3b. Phone No. (include area code)			de)	10. Field and Pool or Exploratory Area		
303 Veterans Airpark Ln., Ste 3000 Midland, TX 79705		(432) 818-1015		Lusk; Bone Spring, South (41460)		
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 660 FSL & 830 FWL UL:M Sec:28 T:19S R:32E				11. County or Parish, State Lea County, NM		
12. CHEC	CK THE APPROPRIATE BOX	(ES) TO INDICATE NATUR	E OF NOTIC	E, REPORT OR OTH	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	Acidize	Deepen ·	Produ	iction (Start/Resume)	Water Shut-Off	
	Alter Casing	Fracture Treat	Reclar	mation	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recon	mplete	Other Corrections for NWO	
	Change Plans	Plug and Abandon	Temp	orarily Abandon		
Final Abandonment Notice	Convert to Injection	Plug Back	☐ Water	ter Disposal		
13. Describe Proposed or Completed O the proposal is to deepen direction. Attach the Bond under which the v following completion of the involv testing has been completed. Final determined that the site is ready fo	ally or recomplete horizontally work will be performed or proved operations. If the operation Abandonment Notices must be final inspection.)	, give subsurface locations and ide the Bond No. on file with E n results in a multiple completic filed only after all requiremen	measured and BLM/BIA. Response or recomplets, including a	d true vertical depths of equired subsequent re- letion in a new interval	of all pertinent markers and zones, ports must be filed within 30 days I, a Form 3160-4 must be filed once	
,					·	
The well sign was put on location	n Thursday, November 15, 2	2012.				
2) Please refer to the attached Site	Security (Facility) Diagram					
3) Updated Water Disposal Information Reck A	nore. Of Ja	Lake SWD Unloading Station	on, Location	- Unit :A, Sec:29, T	:17S, R:31E	

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

12-20-12

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. WSB/OCD | |Z|Z6/2012

Office


Title Regulatory Tech I

Date 11/15/2012

Title & U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Fatima Vasquez

Signature



I. Production Phase Coti)

- 1.) value =1 open
- 2.) Value #3 open
- 3.) Value #4 Sealed Closed
- 4.) Valves on OT2 OT3 OT4
 - A.) Velves #1 Closeo
 - B.) Valves#2 Sealed
 - c.) values #4 sealed closed

II. Sales Phase COTI)

- 1.) Values 1,2,3, Seales Closes
- 2.) Values #4 on otl open
- 3.) Values on ota
 - A. Nalve #1 open
 - B.) value #2 sealed

 - C.) Value #4 Sealed Closed
 - 4.) Values on org or4 Ajvalve #1 closes
 - 8.) Valve = 2 sealed
 - (.) Value #4 Scaled Closes

Apache Corporation

South Lusk 28 Feberal #1 660'FSL & 830' FWL ulm, SEC. 28, T195. R32E LEA COUNTY. HM LSE . NM NM 111963 API #30-025-36992

Hobbs, Nm 88240