

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
June 19, 2008

HOBBS OCD

NOV 20 2013

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-40110
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VB-1510
7. Lease Name or Unit Agreement Name Camel State
8. Well Number 1
9. OGRID Number 013837
10. Pool Name or Wildcat Wildcat; Bone Springs
11. Elevation (Show whether DR, RKB, RT, GR etc.) 3757' GR

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator Mack Energy Corporation	
3. Address of Operator P.O. Box 960 Artesia, NM 88210	
4. Well Location Unit Letter <u>P</u> <u>330</u> feet from the <u>South</u> line and <u>330</u> feet from the <u>East</u> line Section <u>10</u> Township <u>19S</u> Range <u>36E</u> NMPM County <u>Lea</u>	
11. Elevation (Show whether DR, RKB, RT, GR etc.) 3757' GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIALWORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

10/29/2013 Tagged CIBP @ 5283'. Set 1st 25sx plug from 2870-2970', tagged plug @ 2849'. WOC 4 hours. Set 2nd 25sx plug @ 1575-1675'. Notified Mark w/ Hobbs OCD.

10/30/2013 Tagged 2nd plug @ 1412'. Set 3rd 25sx plug @ 250' to surface. Notified Mark w/ Hobbs OCD. Building Dry Hole Marker.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Deana Weaver

TITLE Production Clerk

DATE

11.18.13

Type or print name Deana Weaver

E-mail address: dweaver@mec.com

PHONE: (575)748-1288

For State Use Only

APPROVED BY:

Mary Brown

TITLE

Compliance Officer

DATE

11/20/2013

Conditions of Approval (if any):

NOV 21 2013