				os SOCI	5. Lease Serial No.			
SUNDRY NOTICES AND REPORTS ON WELLS JAN 07 201 Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals					MM19447 6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE – Other instructions on page 2.					7. If Unit of CA/Agreement, Name and/or No.			
T. Type of Well Gas Well Oil Well Gas Well					8. Well Name and No. Exxon Forrest Federal #1			
2. Name of Operator Tempo Energy, Inc					9. API Well No. 30-025-27358			
3a. Address PO Box 1034 Midland, TX 79702	 3b. Phone No. (include area code) 361-649-3891 			10. Field and Pool or Exploratory Area				
 4. Location of Well (Footage, Sec., T.R., M., or Survey Description) P: 660 FEL Section 8, 26S-32E, NMPM 					11. County or Parish, State LEA			
12. CHEC	K THE APPROPRIATE BC	X(ES) TO INDICA	FE NATURE OF	NOTIC	E, REPORT OR OTHER DA	ЛŢĄ		
TYPE OF SUBMISSION TYPE OF AC					ON			
Notice of Intent	Acidize Alter Casing Casing Repair	Alter Casing Fracture Treat Reclamati Casing Repair New Construction Recomple				Water Shut-Off Well Integrity Other		
Final Abandonment Notice	Convert to Injection	Plug Back			orarily Abandon · Disposal			
Dug up area around tanks, flow lines, and well. Dug out around tanks and hauled contaminated soil to deep around tank battery per BLM instructions. All work done by Roadrunner Environmental of Carlsba SEE ATTACHED FOR CONDITIONS OF APPROVAL					ACCEPTED			
					BUREAU OF LAI CARLSBAD	vd managem FIELD OFFICE	ENT	
14. I hereby certify that the foregoing is to	ue and correct. Name (Printe						;	
Frank Pannell		Titl	e President					
Signature france Date 12/13/2013								
[6	THIS SPACE	FOR FEDERA	L OR STATI	E OFF	ICE USE			
Approved by								
Conditions of approval, if any, are attached that the applicant holds legal or equitable ti entitle the applicant to conduct operations	tle to those rights in the subject		Title Office ·		Date			
Title 18 U.S.C. Section 1001 and Title 43 fictitious or fraudulent statements or repre			knowingly and wi	illfully to	make to any department or ag	ency of the United	States any false,	
(Instructions on page 2)								

ROADRUNNER HIRED TO DIG OUT SPILLAGE AND REMOVE CONTAMINANTS FROM THE WELL PAD. ROADRUNNER REMOVED 3' FROM AROUND THE TANKS BUT STAINING STILL APPEARED. PLACE 20 MIL LINER IN AREA TO HELP WITH FUTURE SPILLAGE. SOME SALT CONTAMINATED MATERIAL WAS REMOVED FROM OUTSIDE THE BERMED AREA ALONG WITH THE SOUTH END OF THE WELL PAD. FOR SOME REASON ALL THIS WAS STOCKPILED ON THE WEST SIDE OF THE WELL PAD. THIS IS STILL STOCKPILED ON SITE AND WILL NEED TO BE REMOVED ALONG WITH CONTAMINATION ON WELL PAD.THIS WILL NEED TO BE COMPLETED BY JANUARY 25, 2014 OR NONCOMPLAINCE WILL BE MAILED FOR ANY DEFICIENCIES.