
State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERV	VATION DIVISION	1	Revised 5-27-2004	
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240	1220 South St. Francis Dr. Santa Fe, NM 17555 OCD		WELL API NO. 30-025-28335		
DISTRICT II	Santa i	,HOBBS OCD	5. Indicate Type of Lease		
1301 W. Grand Ave, Artesia, NM 88210			STATE	FEE X	
DISTRICT III		JUL 3 0 2014	6. State Oil & Gas Lease No.		
1000 Rio Brazos Rd, Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agree	ement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLOE SERVED A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)				South Hobbs (G/SA) Unit	
1. Type of Well:	ATTECATION TOKTERMIT (TOILLE	5-101) for such proposais.)	8. Well No. 131		
Oil Well X	Gas Well Other				
2. Name of Operator			9. OGRID No. 157984		
Occidental Permian Ltd. 3. Address of Operator			10. Pool name or Wildcat	Hobbs (G/SA)	
HCR Box 90 Denver City, TX	X 79323				
Unit Letter G : 1383	Feet From The North	Line and 2498	Feet From The East	Line	
Section 4	Township 19-S		8-E NMPM	Lea County	
	11. Elevation (Show whether DF, 3630' RDB	RKB, RT GR, etc.)			
Pit or Below-grade Tank Application	or Closure				
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water					
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material					
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	X ALTERIN	IG CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG &	ABANDONMENT	
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEN	MENT JOB		
OTHER:		OTHER:			
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
1. RUPU & RU. 2. ND wellhead/NU BOP.					
3. POOH w/ESP equipment. Found motor shorted and grounded phase to phase.					
4. RIH w/bit. Tagged @4212. POOH w/bit.					
5. Run back in hole with ESP equipment set on 126 jts of 2-3/8" tubing. Intake set @3964'6. ND BOP/NU wellhead.					
	on and return well to production.				
RUPU 07/01/2014					
RDPU 07/03/2014					
I hereby certify that the information above is constructed or	true and complete to the best of my kno	owledge and belief. I further cer	tify that any pit or below-grade tank	has been/will be	
closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan					
SIGNATURE Melidy	a Ownow	<u> </u>	ive Associate DA	∟ ГЕ <u>07/29/2014</u>	
TYPE OR PRINT NAME Mendy A.	Johnson E-mail address:	mendy_johnson@oxy.c	om TELEPHONE NO	806-592-6280	
For State Use Offly	R. S.	<i>y</i> . ⊤		7/2	
APPROVED BY	HOUN	TITLE DUST.	Dupenson DA	TE 1/30/2014	
CONDITIONS OF APPROVAL IF ANY:			ı	' '	

JUL 3 0 2014

Work Plan Report for Well:SHOU-131G04



Survey Viewer