Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Hobbs

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

Expires: July Lease Serial No.

5. Lease Serial No. NMNM88164

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an
abandoned well. Use form 3160-3 (APD) for such proposals

i. (HOBBS OCD
------	-----------

6. If Indian, Allottee or Tribe Name

	======================================		1999			
SUBMIT IN	C. 1. 5 2014 7. If Unit	or CA/Agreement, Name and/or No.				
1. Type of Well			8. Well Na	une and No. Parsley Afra		
Ø Oil Well ☐ Gas Well [I ALIDA MATTO		PEOL 331		
2. Name of Operator YATES PETROLEUM CO	Contact: DRPORATIONE-Mail: laura@yat	LAURA WATTS espetroleum.com	9. API We Multip	ell No. 30-025-378/3 le-See Attached		
3a. Address 105 SOUTH FOURTH ST ARTESIA, NM 88210	REET	3b. Phone No. (include area cod Ph: 575-748-4272 Fx: 575-748-4585	e) 10. Field a WILD	and Pool, or Exploratory CAT		
4. Location of Well (Footage, S	ec., T., R., M., or Survey Description	i)	11. Count	y or Parish, and State		
MultipleSee Attached			LEA C	COUNTY, NM		
12. CHECK A	APPROPRIATE BOX(ES) TO	O INDICATE NATURE OF	NOTICE, REPORT, C	R OTHER DATA		
TYPE OF SUBMISSION		ТҮРЕ	OF ACTION			
S Nation of February	☐ Acidize	☐ Deepen	☐ Production (Start/F	Resume)		
■ Notice of Intent	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity		
Subsequent Report	Casing Repair	☐ New Construction	☐ Recomplete	Other		
☐ Final Abandonment Notice	ce Change Plans	☐ Plug and Abandon	☐ Temporarily Abane	don Workover Operations		
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal			
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Yates Petroleum Corporation plans to pull RBP and commingle Delaware and Bone Spring as follows: 1. NU BOP. Rig up all safety equipment as necessary. POOH with all production equipment, rods, pump and production string. When releasing the TAC at 8,425 ft, go in and tag top of fill. 2. If fill, TIH with bit and tubing to clean out fill. Circulate clean. If not much fill, may be able to clean it out with the releasing tool. 3. TIH and release RBP at 8,885 ft and POOH. 4. TIH with tubing anchor and seating nipple. Set anchor and hang the tubing off. TIH with pump and rods. Turn the well over to the Production. (DHC-1639) SEE ATTACHED FOR CONDITIONS OF APPROVAL						
14. I hereby certify that the forego	oing is true and correct. Electronic Submission #	2249579 verified by the BLM W ROLEUM CORPORATION, ser ocessing by CATHY QUEEN of Title REG	ell Information System	ELAND MA		
	Committed to AFMSS for pro	ocessing by CATHY QUEEN or	n 06/19/2014 (14CQ01408	BEAU SBAD		
Name (Printed/Typed) LAUF	RA WATTS	Title REG I	REPORTING TECHNI 8	ANCARE		
Signature (Electr	ronic Submission)	Date 06/13				
	THIS SPACE FO	OR FEDERAL OR STATE	OFFICE USE			
_Approved By_EDWARD_EER	NANDEZ	TitlePETROL	EUM ENGINEER	Date 12/08/2014		
	ttached. Approval of this notice does or equitable title to those rights in the conduct operations thereon.		K	C.		
	tle 43 U.S.C. Section 1212, make it a ulent statements or representations a			epartment or agency of the United		

Additional data for EC transaction #249579 that would not fit on the form

Wells/Facilities, continued

 Agreement
 Lease

 NMNM88164
 NMNM88164

 NMNM88164
 NMNM88164

Well/Fac Name, Number 64 PARSLEY ARA FED 01 64 PARSLEY ARA FED 01 **API Number** 30-025-33863-00-S1 30-025-33863-00-S2

LocationSec 26 T23S R32E SESE 760FSL 990FEL
Sec 26 T23S R32E SESE 760FSL 990FEL

KLL INE : PARS			
LUCALIUR: 760 FS	1 1 990 Fri - SEA 71	TILLO AREA: TRITED	PAW DELAWA
	AGE	ESS KSZE	
KB: 3703' ORIG. DRL COMMENTS:	.G./COMPL. DATE:	CASING PROG	
		SIZE/WT./GR./CONN.	DEPTH SET
		113/4" 42 # H-40 Src	630'
1434" \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\	113/4"e630"	5 12" 17" L-80 LTC 5 12" 17" N-80 LTC	7C. 4835' 1872 4983 8,394 10,325
/1" \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	848"e 4835' CMT-1600 SKS, CIRC		Fore
7%" {		Dst *1 .	5006 - 51vo
{\ }\ }	TOC 4200 ±	94°F — 2: DP - 90' 45° 2727' F	SURFACE - 6 MIN, 214 PSI 616 1 120'RH MVO COMMATINI WATER AS + 1300 CC WA(Y,
{			·
	BRUSHY CAMYON Acidize	7000 and 10% IC HCI +25 BS 6,500 and 40,000 11 10.5 BPM 1.	518-520 PS; IS BIN
	AVALON B971-B987 (FRAC-60,000 gd 33# 1390 36 BPM C, 1800 PS/,	34) ACIOIZE - 1500 gal I.	SIA- /2vo PSI urta BC ISIR-ZasoAsi
10,282	(WELL TO SHEL	
1 50 000	1 51/2" @ 10,325 CMT- 55	o 3KS	
•	- SKETCH NOT TO SCALE	4	-12-99 8b 197 M KEITH

- And	
WELL HAVE: PARSLEY ARA FEO HI	FIELD-AREA: TRUTE DRAW DelaWARE BO
LOEMTION: 760 FSL 1 990 FEL SEC 26	7235 Rate 3
GL. 3690 · ZERO: 13 · AG: KO: 3703 · ORIG. DRIG. /COMPL. DATE:	CASING PROGRAM:
COMMENTS:	STZE/WT./GR./CONN. DEPTH SET
	11314" 42# H-40 SIC 630"
[3] LRE	B-16" 32" M-951J-55 STC 4835' \$12" 17" 1-80 LTC 1872 575" 17" N-10 LTC 4983 512 17" T-55 LTC 8,394
1474" []]	511" 17" N-80 FTC 10,325 210" L-80 F.Y* EVE
11" 113/N"CC30" CMT-600 3Ks, C	lac.
B48"e 4835 CMT-1600 SKS, CI	AFTER
7%" } TOC 4200 ±	DST # - 5006 - 5100 GAS TO SURFACE - 6MIN. 94°F - ZZIY PSI DP - 90° 45°01 + 120° R4 M-0 2727' FOMMA'IN WATER
}\	Se syllicas + 23 oocc walv.
\{\langle \langle \tag{\chi}	20.,300
\	
BRUSHY CANYON A	Edize- 2000 and 10% IC HCL + 25 B5 ENL-16,500 & 1 40,000 11 10.5 BPM ISIN-520 PSI CURRENT PHODULTION - 5BO, 65 BW
$\{A \in \mathcal{A}\}$	
AVALON B971- Frac - 60,000 sd 3 36 BPM C, 19	8987 (34) ACIDIZE - 1500 gal ISIA- 1200 PSI 154 138,000 4 20/40 Ollum 1 3gaso 4 20/40 Sutin Bl ISIA-2000ASI 20 1951.
10,282'	49) 2300 GALLONG 102 HCL
51/2" @ 10,325, C	4/0 - 44 1/0 - 14
- SUCTOR NOT 1	——————————————————————————————————————

Conditions of Approval

Sundries dated 6/13/14 and 9/15/2014 Yates Petroleum Corporation Parsley ARA Fed 1 API 3002533863, T23S-R32E, Sec 26

December 8, 2014

- 1. DHC work approved as written
- 2. Subject to like approval by the New Mexico Oil Conservation Division.
- 3. Surface disturbance beyond the existing pad must have prior approval.
- 4. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 5. Functional H₂S monitoring equipment shall be on location.
- 6. A minimum of 3000 (3M) BOPE shall be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M) Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 7. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 8. File intermediate **subsequent sundry** Form 3160-5 within 30 days of any interrupted workover procedures and a complete workover subsequent sundry.
- 9. Submit the BLM Form 3160-4 **Recompletion Report** within 30 days of the date all BLM approved procedures are complete.
- 10. Workover approval is good for 90 days (completion to be within 90 days of approval). A legitimate request is necessary for extension of that date.

EGF 120814