

Submit 1 Copy To Appropriate District Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised July 18, 2013

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-28353
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name South Hobbs (GSA) Unit
8. Well Number 150
9. OGRID Number 157984
10. Pool name or Wildcat Hobbs (GSA)
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3622' KB

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator Occidental Permian Ltd.	
3. Address of Operator P.O. Box 4294 Houston, TX 77210	
4. Well Location Unit Letter <u>D</u> : <u>330</u> feet from the <u>North</u> line and <u>1220</u> feet from the <u>West</u> line Section <u>10</u> Township <u>19S</u> Range <u>38E</u> NMPM Lea County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3622' KB	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐  
CLOSED-LOOP SYSTEM ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐  
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

MI x RUPU. ND WH x NU BOP. RIH x pick up 4 3/4" bit x 124jts x tag TOC @ 3985'. RUPS x drilled cement 3985' - 4007' @ CIBP. Drilled on CIBP pushing it to 4283' x RDPS x SION. Killed well x RIH tubing x tag @ 4321'. RUPS x drill 4321' to TD 4349' x clean well. POOH tubing x 4 3/4" bit. RUWL shoot perfs 4293' - 4330' x RDWL. RIH pkr x tubing x set pkr @ 4050'. Run acid job with 6000 gal 15% NEFE x 2000 bbls fresh water. Killed well x POOH tubing x pkr. RIH with 5 1/2" rbp x set @ 4050'. POOH 125 jts x retv head. RUWL x RIH Schlumberger logging tool to 4045' x log to surface x RDWL. Unset rbp x POOH tubing and rbp. RU spooler x assembled esp x RD spooler. ND BOP x RD x MO location. Well started producing 8/1/15.

Spud Date:

02/18/15 (RUPU)

Rig Release Date:

02/26/15 (RDPU)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE April Hood TITLE Regulatory Coordinator DATE 09/24/15

Type or print name April Hood E-mail address: April\_Hood@oxy.com PHONE: 713-366-5771

For State Use Only

APPROVED BY: Marky Brown TITLE Dist. Supervisor DATE 9/28/2015

Conditions of Approval (if any):

09/13/2015