Submit 1 Copy To Appropriate District Office		f New Mexico		Form C-103	
District I (575) 393-6161 (1625 N. French Dr., Hobbs, NM 88240	Energy, Mineral	s and Natural Resource	WELL AP	Revised August 1, 2011 I NO.	
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSER	VATION DIVISION		30-025-20882	
District III - (505) 334-6178		th St. Francis Dr.	5. Indicate	Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa I	Fe, NM 87505		il & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505			B-1839-1		
(DO NOT USE THIS FORM FOR PROPODIFFERENT RESERVOIR. USE "APPLI		EPEN OR PLUG BACK TO A		Jame or Unit Agreement Name orieta East Unit	
PROPOSALS.) 1. Type of Well: Oil Well X	Gas Well Other	HOBBS OCD	8. Well Nu	umber 003	
2. Name of Operator ConocoPhilli	ips Company	JAN 1 9 2016	9. OGRID	Number 217817	
3. Address of Operator P. O. Box 51810		RECEIVED	10. Pool na	ame or Wildcat	
Midland, T	X 79710		Vacuum; Gl	lorieta	
4. Well Location Unit Letter E:	2310 feet from the	e North line and	1 330 f	eet from the West line	
Section 27	Township 1		NMPM	County Lea	
		whether DR, RKB, RT, GR		A CONTRACTOR OF THE SECOND	
EL AU TERRET DE LA SERVICIO				对是我从外看到你们的企业不明显是	
12. Check	Appropriate Box to I	ndicate Nature of No	tice Report or (Other Data	
NOTICE OF IN	NTENTION TO: PLUG AND ABANDO			T REPORT OF: ☐ ALTERING CASING ☐	
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS. P AND A			
PULL OR ALTER CASING	MULTIPLE COMPL	☐ CASING/CE	MENT JOB		
DOWNHOLE COMMINGLE					
OTHER:		□ OTHER:			
 Describe proposed or comp of starting any proposed we proposed completion or rec 	ork). SEE RULE 19.15.7			ent dates, including estimated date ttach wellbore diagram of	
ConocoPhillips Company would			er cut & facility w	ater handling capacity.	
Attached is a procedure & a curre	ent/proposed wellbore sci	nematic.			
			This is the same		
		Condit	ion of Annrova	le notify	
	Condition of Approval: notify				
	OCD Hobbs office 24 hours				
		prior of r	unning MIT Te	st & Chart	
Spud Date:	Rio	Release Date:			
Sput Dute.		Tereuse Date.			
2.69					
I hereby certify that the information	above is true and comple	ete to the best of my know	vledge and belief.		
SIGNATURE Thornes	Tagers_TIT	TLE Staff Regulatory Tec	hnician	DATE 01/13/2016	
Type or print name Rhonda Rogers	E-n	nail address: rogerrs@co	nocophillips.com	PHONE: <u>(432)688-9174</u>	
For State Use Only	MK	Dirt C	0	1/20/2011	
APPROVED BY: Conditions of Approval (if any):	A SLOWY FIT	LE NILL DU	HEWBOU	DATE 1/20/2016	
conditions of represent (it mig).				JAN 2 1 2016 fm	

VGEU 26-03 TA WELLBORE API #30-025-20882



Project Scope

Justification and Background: TA wellbore

This well has been down since 5/13/2015 due to having a high water cut and facility water handling capacity. This well has a high fluid level (2710' FAP) and needs to be converted to an ESP. However, due to the uncertainty of how much fluid the 2015 VGEU New Drill Program will provide to the battery, which started in September, the increased water production that would occur from the conversion the facility would be operating at or beyond its capacity. Therefore, the 2015 VGEU New Drills will be put on production and the facility upgrade will be re-evaluated before this ESP conversion.

Perforations					
Type	Formation	Top	Bottom		
Perforations	Glorieta	6,067	6,234'		
PBTD	6,170'				
TD	6,275'				

Prior to Rigging up (1-2 weeks)

- Confirm we have State NOI approval to TA wellbore
- ~83 joints of 2 3/8" 4.7# tubing for length to set CBP

Well Service Procedure:

- 1) MIRU pulling unit. Kill well.
- 2) TOOH w/ rods & pump. LD rods and pump.
 - a. Pick up rods.
 - b. Send pump to be inspected, repaired, and put back as spare. If pump is junk or uneconomical to repair, will not repair or build new.
- 3) NDWH, NUBOP. Test BOP.
- 4) Release TAC & TOOH w/ Tbg. LD TAC. Stand Tbg back in Derrick.
- 5) MI lay down machine. PU & TIH w/ bit, scraper sized for 11.6# 4 ½" casing, and ~83 Jts of 2 3/8" 4.7# from inventory to PBTD @ 6,170'. Release lay down machine. TOOH & LD bit and scraper. Stand back Tbg in Derrick.
 - a. Record tag depth in WV
- 6) PU & TIH w/ CBP. Set CBP @ 6,017' (50' from top perf).
- 7) RU pump truck. Load well bore w/ brine and test CBP to 500 psi surface pressure. If CBP holds then proceed to circulate packer fluid and chart pressure.
- 8) RU pump truck. Circulate packer fluid to surface (6,017' x 0.0155 bbl/ft = 94 bbls).
- 9) MI lay down machine. TOOH & lay down Tbg. Release lay down machine.
 - a. Send Tbg into be inspected
 - b. Send ~83 Jts of 2 3/8" Tbg back to inventory

HOBBS OCD

CURRENT SCHEMATIC

VACUUM GLORIETA EAST UNIT 026-03

JAN 1 9 2016

RECEIVED

