

Submit 1 Copy To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
October 13, 2009

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-03382
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name State WE F
8. Well Number 1
9. OGRID Number 873
10. Pool name or Wildcat Eumont Yates 7 RQ

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☒ Gas Well ☐	
2. Name of Operator Apache Corp.	
3. Address of Operator P O box Drawer D Monument NM 88265	
4. Well Location Unit Letter <u>N</u> : 1980 feet from the <u>W</u> line and 3300 feet from the <u>S</u> line Section <u>1</u> Township <u>21S</u> Range <u>35E</u> NMPM Lea County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3536' DF	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

E-PERMITTING <SWD INJECTION> CONVERSION <u>MB</u> RETURN TO <u>TA</u> CSNG <u>ENVIRO</u> CHG LOC INT TO PA <u>P&A NR</u> P&A R	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ P AND A ☐ CASING/CEMENT JOB ☐ OTHER: <u>TA TEST</u> ☒
---	---

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Perfs 3338'-3800'

This Approval of Temporary
Abandonment Expires 2/2/2021

1. MIRU. POOH & LD RODS. POOH TBG
2. SET CIBP @ 3270'. DUMP BAIL 35' CMT. ON CIBP.
3. LOAD CSG W/ PKR FLUID.
4. TEST CSG TO 540 # FOR 30 MINUTES.
5. NOTIFY OCD 24 HRS BEFORE TA TESTING.
6. MEET OCD REP. GEORGE BOWER. PRESSURE UP ON CSG TO 570#. RECORD TEST ON CHART RECORDER. ENDING PRESSURE 560#. REQUEST TA STATUS FOR WELL. SEE ATTACHED CHART.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Joel Sisk TITLE Sr. Pumper DATE 2/2/17

Type or print name Joel Sisk E-mail address: joelsisk@apacheccorp.com PHONE: 575-441-0793

For State Use Only

APPROVED BY: Mary Brown TITLE AO/II DATE 2/8/2017
Conditions of Approval (if any):

Graphic Controls



DATE

2/26/07

BR 2222

START

0

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48

49

50

51

52

53

54

55

56

57

58

59

60

61

62

63

64

65

66

67

68

69

70

71

72

73

74

75

76

77

78

79

80

81

82

83

84

85

86

87

88

89

90

91

92

93

94

95

96

97

98

99

100

101

102

103

104

105

106

107

108

109

110

111

112

113

114

115

116

117

118

119

120

121

122

123

124

125

126

127

128

129

130

131

132

133

134

135

136

137

138

139

140

141

142

143

144

145

146

147

148

149

150

151

152

153

154

155

156

157

158

159

160

161

162

163

164

165

166

167

168

169

170

171

172

173

174

175

176

177

178

179

180

181

182

183

184

185

186

187

188

189

190

191

192

193

194

195

196

197

198

199

200

201

202

203

204

205

206

207

208

209

210

211

212

213

214

215

216

217

218

219

220

221

222

223

224

225

226

227

228

229

230

231

232

233

234

235

236

237

238

239

240

241

242

243

244

245

246

247

248

249

250

251

252

253

254

255

256

257

258

259

260

261

262

263

264

265

266

267

268

269

270

271

272

273

274

275

276

277

278

279

280

281

282

283

284

285

286

287

288

289

290

291

292

293

294

295

296

297

298

299

300

301

302

303

304

305

306

307

308

309

310

311

312

313

314

315

316

317

318

319

320

321

322

323

324

325

326

327

328

329

330

331

332

333

334

335

336

337

338

339

340

341

342

343

344

345

346

347

348

349

350

351

352

353

GL='
KB=3565'
Spud: 5/5/54

Apache Corporation – State WE F #1

Wellbore Diagram – Current Status

Date : 12/8/2016

API: 30-025-03382

Surface Location K. Grisham




3300' FSL & 1980' FWL, Unit F
Sec 35, T21S, R35E, Lea County, NM

Surface Casing
13-3/4" @ 312' w/ 300 sx to surface

Hole Size
=13-3/4"

Hole Size
=8-3/4"



1/17: Set CIBP @ 3270' & cap with 35' cmt.

6/54: Perf'd fr/ 3680-3720'; 3750-3760'; 3790-3800'. Sand oil frac'd w/ 7500 gals oil & 7500# sand.
4/58: DO cmt plug fr/ 3845-3850' push bridge plug fr/ 3850-3960', & DO plug fr/ 3960-3970'.
7/78: TA Eumont perfs.
10/80: Sqz'd Eumont perfs fr/ 3338-3560' w/ 760 sxs cmt.
11/80: CO fill in 7" csg fr/ 3643-3970'. Acidize Eumont fr/ 3680-3970' w/ 1000 gals 20% acid.
6/81: Set CIBP @ 3845' perf fr/ 3680-3800' w/ 200 grams/ft. Acidized w/ 2000 gals 15% NEFE.

Production Casing
7" @ 4150' w/ 800 sxs. TOC @ 2097'

PBTD = 3845'
TD = 4150'