

Submit 1 Copy To Appropriate District Office

District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
October 13, 2009

WELL API NO. <b>30-025-20227</b>	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. <b>B-9505</b>	
7. Lease Name or Unit Agreement Name <b>New Mexico AT State</b>	
8. Well Number <b>6</b>	
9. OGRID Number <b>213190</b>	
10. Pool name or Wildcat <b>Saunders Permo Upper Penn</b>	
4. Well Location Unit Letter <b>F</b> : <b>1980</b> feet from the <b>N</b> line and <b>1980</b> feet from the <b>W</b> line Section <b>15</b> Township <b>14S</b> Range <b>33E</b> NMPM County <b>Lea</b>	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) <b>4208 GR</b>	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> 2. Name of Operator <b>CrownQuest Operating, LLC</b> 3. Address of Operator <b>P.O. Box 53310, Midland, TX 79710</b>	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms.

Restoration Due By **03-07-2018**

INT TO PA  
P&A NR **Am. X**  
P&A R

IBSEQUENT REPORT OF:

DRK ☐ ALTERING CASING ☐  
DRILLING OPNS. ☐ P AND A ☒  
ENT JOB ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

02/28/17 MIRU Plugging equipment, dug out cellar, ND well head, NU BOP. RIH & Pump'd 30 bbls H2O @ 9310'. Spot'd 25 sx class H cmt @ 9310-8932'. WOC. No tag. Re-spotted 25 sx class H cmt w/ magma fiber (MF) @ 9310-8932'. WOC. 03/02/17 No tag. Pump'd 20 bbls H2O w/ 3 sxs MF & let set for 30 mins. Spot'd 30 sx class H cmt @ 9310-8856'. WOC. No tag. Pump'd 15 bbls H2O w/ 2 sxs MF & let set for 30 mins. Spot'd 30 sx class H cmt w/ MF @ 9310-8856'. WOC. 03/03/17 Tag'd plug @ 8510'. Circ'd hole w/ 256 bbls MLF. Pressure test'd csg, 0 psi. Spot'd 25 sx class C cmt @ 7000-6622'. WOC. Tag'd plug @ 6760'. 03/06/17 Set 4 1/2 CIBP @ 4650'. Circ'd hole w/ 28 bbls MLF. Pressure test'd csg, held 500 psi. Spot'd 25 sx class C cmt @ 4650-4272'. Spot'd 35 sx class C cmt @ 4190-3871'. WOC. 03/07/17 Tag'd plug @ 3900'. Spot'd 35 sx class C cmt @ 2650-2478'. Spot'd 25 sx class C cmt @ 1800-1677'. WOC. Tag'd plug @ 1675'. Perf'd csg @ 416'. Sqz'd 50 sx class C cmt @ 416-316'. WOC. 03/08/17 Tag'd plug @ 314'. Perf'd csg @ 100'. Sqz'd 40 sx class C cmt @ 400-surface. Rig'd down, moved off. 3/11/17 Moved in backhoe & welder, dug out cellar. Cut off well head. Welded on "Above Ground DHM". Backfilled cellar. Cut off deadmen. Cleaned location & moved off.

Spud Date:

02/28/2017

Rig Release Date:

03/08/2017

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Lease Manager

DATE 03/15/2017

Type or print name Saul Leyva

E-mail address: sleyya@crownquest.com

PHONE: 432-559-9066

For State Use Only

APPROVED BY:

TITLE P.E.S.

DATE 03/27/2017

Conditions of Approval (if any):