		OCD	HOBBS			
	UNITED STATES EPARTMENT OF THE I	TERIOR	ERIOR		FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018	
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			5. Lease Serial No. NMNM78273			
			6. If Indian, Allottee	or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or CA/Ag	eement, Name and/or	
1. Type of Well				8. Well Name and No.		
Oil Well 🔲 Gas Well 🗋 Other				LUCY FEDERAL 2		
2. Name of Operator READ & STEVENS Contact: KELLY BARAJAS E-Mail: kbarajas@read-stevens.com				9. API Well No. 30-025-40055		
3a. Address P. O. BOX 1518 ROSWELL, NM 88202	Ph: 575-624-3760			r Exploratory Area		
4. Location of Well (Footage, Sec.,)	11. County				
Sec 14 T20S R34E 1980FSL 330FWL			LEA COUNTY, NM			
12. CHECK THE A	APPROPRIATE BOX(ES)	TO INDICATE NATU	JRE OF NOTICE	E, REPORT, OR OT	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
□ Notice of Intent	Acidize	Deepen	_	ction (Start/Resume)	□ Water Shut-0	
Subsequent Report	□ Alter Casing □ Casing Repair	□ Hydraulic Frac □ New Construct			Well Integrit	
Final Abandonment Notice	Change Plans	□ Plug and Aban		prarily Abandon		
	Convert to Injection	Plug Back	□ Water			
13. Describe Proposed or Completed O If the proposal is to deepen directio Attach the Bond under which the w following completion of the involvy testing has been completed. Final A determined that the site is ready for	nally or recomplete horizontally, ork will be performed or provide ed operations. If the operation rea Abandonment Notices must be fil	give subsurface locations and the Bond No. on file with B sults in a multiple completion	d measured and true LM/BIA. Required s n or recompletion in a	vertical depths of all pert ubsequent reports must b a new interval, a Form 3	inent markers and zon be filed within 30 days 60-4 must be filed on	
1/26/2017 - 2/10/2017						
RU swab. BFL at 1800 FFS Minimal gas show after each 1st swab. 50- 0% oil cut res Sandline broke at rope socke w/cable. Tag up at 3487'. R Circ hole clean. RD. TOH w tbg. Tag up at 3510'. RU sw onto & release RBP. RD. T tbg. Tag PBTD at 3809'. To banging at 3345' above perfection	swab. Rec 51 BLW & 10 t of the day. Rec 17 BW & et. Release pkr. Equalize U swivel, stripper head. E //tbg & shoe. Swab mandr vivel and stripper head. Wi OH w/2 7/8" tbg laving dwr	BO. RU swab. BFL at 16 BO. RU swab. Fra tbg & csg. TOH w/tbg. stablish circ. Wash sa el in shoe. LD shoe. T ash down to 3550'. Cir RBP. TIH w/notch co er & 109 ints 2 7/8" tbc	1000 FFS. 100% c sand at 2000 Ff TIH w/4 3/4" OE nd dwn to 3507'. TIH w/retrieving hu c hole clean. Lat llar & 119 jnts 2 7 . Leave cmt reta	6 oil cut on FS. 9 shoe ead, ch /8"		
14. I hereby certify that the foregoing	Electronic Submission # For RE	AD & STEVENS, sent to	LM Well Information			
	Electronic Submission # For RE/ Committed to AFMSS for	AD & STEVENS, sent to processing by DEBORA	LM Well Information	2/15/2017 ()		
14. I hereby certify that the foregoing Name (Printed/Typed) KELLY E	Electronic Submission # For RE/ Committed to AFMSS for	AD & STEVENS, sent to processing by DEBORA Title	LM Well Information the Hobbs H MCKINNEY on 0	2/15/2017 ()	XD	
14. I hereby certify that the foregoing Name (Printed/Typed) KELLY E	Electronic Submission # For RE/ Committed to AFMSS for p BARAJAS	AD & STEVENS, sent to processing by DEBORA Title	LM Well Information the Hobbs H MCKINNEY on 0 CCEPTED 02/15/2017 TATE OFFICE I	2/15/2017 () FOR RECOR	XD	
14. I hereby certify that the foregoing Name (Printed/Typed) KELLY E Signature (Electronic	Electronic Submission # For RE/ Committed to AFMSS for p BARAJAS	AD & STEVENS, sent to processing by DEBORA Title Date C	LM Well Information the Hobbs H MCKINNEY on 0 REPORT PREPA CCEPTED 12/15/2017	2/15/2017 () FOR RECOR	Date	
14. I hereby certify that the foregoing Name (Printed/Typed) KELLY E	Electronic Submission # For RE/ Committed to AFMSS for p BARAJAS Submission) THIS SPACE FC	AD & STEVENS, sent to processing by DEBORA Title Date 0 OR FEDERAL OR S	LM Well Information the Hobbs H MCKINNEY on 0 CCEPTED 12/15/2017 TATE OFFICE I APR BUREAU OF L	2/15/2017 () RER FOR RECOF JSE 10, 2017 Ward AND MANAGEMEN		
14. I hereby certify that the foregoing Name (Printed/Typed) KELLY E Signature (Electronic Approved By Conditions of approval, if any, are attack tertify that the applicant holds legal or e	Electronic Submission # For RE/ Committed to AFMSS for p BARAJAS Submission) THIS SPACE FC end. Approval of this notice does quitable title to those rights in the duct operations thereon. 3 U.S.C. Section 1212, make it a	AD & STEVENS, sent to processing by DEBORA Title Date Date C DR FEDERAL OR S 	LM Well Information the Hobbs H MCKINNEY on 0 REPORT PREPA INCEPTED 12/15/2017 TATE OFFICE IN APR APR BUREAU OF L CARLSBA	2/15/2017 () RER FOR RECOF JSE 10, 20/7 Ward AND MANAGEMEN D FIELD OFFICE	r	

.

Additional data for EC transaction #367091 that would not fit on the form

32. Additional remarks, continued

4

Pump 25 bbls wtr. Set cmt retainer at 3550'. Pump 13 bbls ahead to establish rate and follow w/200 sxs C-Neat cmt at 14.8#/gal. Wash to reverse pit. Displace w/14.5 bbls wtr and walk into 1005# squeeze. Sting out retainer. PU 5' above retainer and reverse circ 6 bbls cmt to reverse pit. TOH w/workstring. TIH w/2 7/8" x 30' TBPMA, 2 7/8" perf'd sub, 2 7/8" OD seating nipple & 110 jnts 2 7/8" tbg. NDBOP. NUWH. EOT @ 3499'. Seating nipple @ 3463'. TIH w/2 1/2" x 1 1/4" x 16' pump, 137 3/4" rods & 1 1/4" x 26' polished steel rod w/1 1/4"x1 1/2" x 16' polish rod liner. Seat & space pump. Hang well on. Well producing.