811 S. I <u>District</u> 1000 R	First St., A III io Brazos IV . St. Franc	Dr., Hobbs, NM 88240 Dr., Hobbs, NM 88240 MINOR DE CEIVED IS Dr., Santa Fe, NM RECEIVED MINOR DE CEIVED See Rule 19.15.18.12 NMAC and Rule 19.15.7.37 NMAC) State of New Mexico Energy Minerals and Natural Resources Form C-129 Revised August 1, 2011 Submit one copy to appropriate District Office Submit one copy to appropriate District Office
	А.	Applicant Matador Production Company
		whose address is 5400 LBJ Freeway, Ste. 1500, Dallas, TX 75240
		hereby requests an exception to Rule 19.15.18.12 for 90 days (beginning 11/12/18) days or until
		, Yr, for the following described tank battery (or LACT):
		Name of Lease Marlan Downey State 9 TB Name of Pool ROCK LAKE; BONE SPRING, SOUTH (52769
		Location of Battery: Unit Letter DSection _09 _Township _23SRange35E
		Number of wells producing into battery (1) 30-025-44201, Marian Downey 9 23 35 AR #111H
	B.	Based upon oil production of
		of gas to be flared is 500MCF; Value per day.
•	C.	Name and location of nearest gas gathering facility:
		Lucid Energy Delaware, LLC
	D.	Lucid Energy Delaware, LLC   DistanceEstimated cost of connection
	D. E.	
		DistanceEstimated cost of connection
		DistanceEstimated cost of connection This exception is requested for the following reasons: _Flaring due to plant/pl and compressor
		DistanceEstimated cost of connection This exception is requested for the following reasons: _Flaring due to plant/pl and compressor
		DistanceEstimated cost of connection This exception is requested for the following reasons: _Flaring due to plant/pl and compressor
I herei Divisi	E. RATOR by certify on have t	DistanceEstimated cost of connection This exception is requested for the following reasons: Flaring due to plant/pl and compressor issues.
I heret Divisio is true	E. RATOR by certify on have t	DistanceEstimated cost of connection This exception is requested for the following reasons: Flaring due to plant/pl and compressor issues. 
I heret Divisio is true Signa Printe	E. RATOR by certify on have t and com ature ed Nam	Distance
I heret Divisio is true Signa Printe & Tit	E. RATOR by certify on have t and com ature ed Nam tle	DistanceEstimated cost of connection This exception is requested for the following reasons: Flaring due to plant/pl and compressor issues.

\* Gas-Oil ratio test may be required to verify estimated gas volume.