

Submit 1 Copy To A	Appropriate Distric	t		State of N	lew Me	xico		Form C-10)3	
Office					and Natural Resources			Revised August 1, 20	<u>11</u>	
1625 N. French Dr., Hobbs, NM 88240							WELL API N 30-025-3075			
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISIO							5. Indicate T		\neg	
District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 1000 Rio Brazos Rd., Aztec, NM 87410							STAT	E 🛛 FEE 🗌		
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM							6. State Oil a	& Gas Lease No.		
87505										
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A							7. Lease Nar	me or Unit Agreement Name		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH							Lovington Sa	an Andres Unit	1	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SLEN PROPOSALS.) 1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other TBBS							8. Well Num			
							9. OGRID N	lumber		
Chevron Midcontinent, L.P.				APR 2 3 2019			241333			
3. Address of Operator			Ы	RECEIVED			ne or Wildcat			
6301 Deauville Blvd., Midland, TX 79706					BECEIVED			n, Grayburg-San Andres	_	
4. Well Location RECEI										
Unit Letter N : 1283 feet from the SOUTH line and 2527 feet from the WEST line Section 31 Township 16S Range 37E, NMPM, County Lea										
11. Elevation (Show whether DR, RKB, RT, GR, etc.)										
			3816' G	,	,		·			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data										
N		-			18.	911		REPORT OF:		
NOTICE OF INTENTION TO: SUB									٦	
TEMPORARILY ABANDON					COMMENCE DRILLING OPNS. P AND A			5		
PULL OR ALTE			MULTIPLE	COMPL		CASING/CEMEI	NT JOB [
DOWNHOLE CO	OMMINGLE				_	071150		_		
OTHER:	nronocod or o	omnl	atad oparativ	one (Clearly	stata all r	OTHER:	nd give pertinen	t dates, including estimated d	lata	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of										
proposed completion or recompletion. 13 3/8" 48# @ 395': TOC @ surface; 8 5/8" 24# @ 2053': TOC @ 710' (Calc); 5 1/2"										
15.5# @	5390': TOC (-	• •							
_		ievro	n USA INC	2 respectfull	y reques	ts to abandon thi	is well as follow	ws:		
1. Pull rod	•									
2. Set CIBP @ 4600'										
	3. Pressure test casing to 500 psi for 10 minutes. If pressure test was successful, spot MLF. If pressure test was									
unsuccessful, spot MLF after first cement plug. 4. Spot 90 sx CL C cement f/ 4600' t/ 3818' (San Andres, Grayburg, Penrose, Queen). If pressure test in Step 3 was										
4. Spot 90 sx CL C cement if 4600° to 3818° (San Andres, Grayourg, Penrose, Queen). If pressure test in Step 3 was unsuccessful, WOC, tag, pressure test, & spot MLF. If pressure test in Step 3 was successful, do not WOC & tag.										
5. Spot 45 sx CL C cement f/ 3360' t/ 2973' (7 Rivers, Yates)										
6. Spot 35 sx CL C cement f/ 2174' t/ 1890' (T. Salt, Shoe, Rustler)										
7. Perf & squeeze 325 sx CL C cement f/ 445' t/ surface (Shoe, Fresh Water)										
8. Verify cement to surface. Cut all casings & anchors & remove 3' below grade. Weld on dry hole marker. Clean										
location				0			6	5		
I hereby certify th	at the informa	tion a	bove is true	and complete	to the be	est of my knowled	lge and belief.			
				4/22/2019						
						See Attached				
X Nick Glann or										
					-	Or	nditions of	Abbio		
	Nick Glann	Decion	• • • • • • • • • • • • • • • • • • • •							
	P&A Engineer/F Signed by: Nick				E		harman ann D	LIONE, 422 697 7796 (* 85 *	~)	
SIGNATURE For State Use On		. 0.01.	•		E-mail	address: <u>nglann(a</u>	cnevron.com	HONE: <u>432-687-7786 (office</u>	र्घ	
· · · ·		ノ	-		<u>^</u>	n' ·	$\wedge M \cdot M$	U_72 10		
APPROVED BY:	: Kerry	<u></u> ፓሪ	the		<u> </u>	mpliance	U ffrent	DATE 4-23-19		
Conditions of Ap	nroval (if anv)	·				V	ĮŪ			

LSAU 60 CURRENT WELLBORE DIAGRAM



LSAU 60 PROPOSED WELLBORE DIAGRAM



GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. <u>Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent</u>. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'. Plugs should be no more than 3000' apart
- 9) Site remediation due within one year of well plugging completion.