Submit I Copy Office	To Appropriate District		State of New Mexico			Form C-103			
District 1 – (575) 393-6161 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240						Revised July 18, 2013  WELL API NO. 30-025-33398			
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 District III - (505) 334-6178  OIL CONSERVATION DIVISION 1220 South St. Francis Dr.						5. Indicate Type of Lease			
1000 Rio Brazo	District III - (505) 334-6178  1000 Rio Brazos Rd., Aztec, NM 87410  District IV - (505) 476-3460  1220 S St. Francis Dr. Santa Fe NM					STATE FEE 6. State Oil & Gas Lease No.			
87505 C 2019						NM-86923			
(DO NOT USE DIFFERENT R	SUNDRY NOT THIS FORM FOR PROP ESERVOIR. USE "APPL	7. Lease Name or Unit Agreement Name  Bitsy Federal SWD							
1. Type of V	Well: Oil Well		8. Well Number 1						
2. Name of	Operator Foundation Energy	9. OGRID	9. OGRID Number						
3. Address of		10. Pool name or Wildcat  Delaware							
4. Well Loc		itu, buite 050, Add			Dela		•		
Uni	t LetterH_		n theNorth		_660	_feet from the _	_Eastline		
Sec	tion 7	Townsh			North E	NMPM	County Lea		
		3,550° GL	ow whether DR	, RKB, RT, GR, etc.	,				
	12. Check	Appropriate Box	to Indicate N	lature of Notice,	Report or	Other Data			
		NTENTION TO:		SUB	SEQUENT REPORT OF:				
PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WOR						_	ING CASING		
TEMPORARILY ABANDON						S.□ PAND. □	A , L		
	E COMMINGLE			OAOIIIO/OEIIIEII	1 000				
	OOP SYSTEM		<b>1927</b>	07:175			_		
	d Delaware Injection ribe proposed or com		Ziearly state all	OTHER:	d give nertin	ent dates, includ	Ling estimated date		
of sta	arting any proposed vosed completion or re	vork). SEE RULE 19							
	r No. SWD-1156 dated No. 1 as a produced water						) to utilize the Bitsy		
This well is cur	rently completed as a p	roduced water disposal	well through per	forations from 5301-5	637, and 6166	-6206 ft. In order	to increase		
injectivity and from 6060 to 60	reduce the injection pre 085 and 6100 to 6165 fover, all additional perfo	ssure, Foundation Energet. The exact location	gy Management, of the additional	LLC proposes to add a perforations, which is	injection perfo not known as	rations in the Del this time will be	aware formation determined by log		
Upon completion perforations.	on of perforating and ac	idizing, plastic-coated	injection tubing w	vill be set in a packer l	ocated within	100 ft of the uppe	rmost injection		
Attached is a sp	pecific procedure descri	bing the proposed oper	ations.						
Spud Date:	6/3/2019		Rig Release D	ate: 6/6/2019					
I hereby certif	fy that the information	prabove is true and co	omplete to the h	est of my knowledg	e and belief.				
	M	[]	//c	() 1F	S , ,	<i>-</i>	-/1/10		
SIGNATURE	- CAMMA	<del>3</del> 7/4	TITLE #	or jusulagory	11150	DATE_S	115/17		
Type or print For State Use		s MOTH	E-mail addres	s: SW-16	paros hinem	PHONE: _	1916-526-5597		
APPROVED	BY:		TITLE	Λο.,		DATE_	1/19/19		
	Approval (if any):								

### **Bitsy Federal #1 SWD**

Sand Dunes

Add Perfs to Increase Injection Capacity and Lower Pressure Lea, County NM

#### Casing /Tubular Details and Capacities:


TUBULAR	SIZE	GRADE	DEPTH (ft)	WEIGHT (ppf)	CEMENT (sx)	TOC (ft)	
Surface Casing	13-3/8"	H-40	858	48	650	SFC	Circ
Intermediate Casing	8-5/8"	J-55	4338	32	1500	SFC	Circ
Production Casing	5-1/2"	K-55	9442	17	1330	SFC	Circ
Producing Tubing	2- 7/8"	IPC	5225	6.4	n/a	n/a	n/a

#### **Procedure:**

- 1. MIRU WO Rig
- 2. Kill well if necessary, using 2% KCL.
- 3. ND WH. NU BOP
- 4. Unseat Packer, PU joints and lower tubing to tag for fill.
- 5. TOOH with TBG. Tally as POOH and note tagged depth.
- 6. If fill is covering existing perfs, cleanout to TD before proceeding to next step.
- 7. MIRU wireline
- 8. RIH with 3 1/8" gun and perf new injection perfs from 6060-6085 and 6100-6165.
- 9. POOH with WL guns
- 10. RD Wireline
- 11. PU and RIH with redressed packer and RIH with tubing.
- 12. Hydrotest as RIH to 6000 psi.
- 13. Set packer above new perfs at +/- 6030'
- 14. MIRU acid crew and test flowlines
- 15. Pump acid job according to pump schedule. 10,000 gals 7.5% NEFE HCl w/ scale inhibitor, clay stabilizer and ball sealers.
- 16. RDMO acid crew.
- 17. Unset packer and pull up to set above all perfs. Set packer at 5225'.
- 18. Pressure test packer is holding to 500 psi and 1000 psi for 10 min each.
- 19. Perform injection test to determine injection rate and pressure.
- 20. RDMO Wo Rig.
- 21. Reconnect equipment for disposal.

## **Bitsy Federal 1**

**Current WBD** 



# Bitsy Federal 1 Proposed WBD

