Office <u>District I</u> - (575) 393-6161	State of New Mexico	Form C-103
District 1 (3/3/3/3/3-0101	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II – (575) 748-1283 811 S. First St., Artesia, NM 8821	OIL CONSERVATION DIVISION	30-025-26221
District III – (505) 334-6178		5. Indicate Type of Lease
1000 Rio Brazos Rd., Azteo 87410	Conto Es NIM 97505	STATE FEE
District IV - (505) 476-2469	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
District III – (505) 334-6178 1000 Rio Brazos Rd., Azteon 87410 District IV – (505) 476-3460 1220 S. St. Francis Da Canta Fe, Niv. 87505	ζŌ	
	ES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PHOPOSA	ALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE PLICA	ATION FOR PERMIT" (FORM C-101) FOR SUCH	QUAIL QUEEN UNIT
PROPOSALS.)	See Well Code of DURGTOR	8. Well Number #3Y
7.1	Gas Well Other INJECTOR	
2. Name of Operator		9. OGRID Number
CHEVRON USA INC 3. Address of Operator		4323
3. Address of Operator 1616 W. BENDER BLVD HOBBS, NM 88240		10. Pool name or Wildcat
	685, NM 88240	QUAIL QUEEN
4. Well Location		
Unit Letter I: 184	1_feet from the <u>SOUTH</u> line and <u>759</u> fee	t from the <u>EAST</u> line
Section 11	Township 19S Range 34E NM	MPM County LEA
	11. Elevation (Show whether DR, RKB, RT, GR, etc.	
	3960' GL	
12 Chook As	opropriate Box to Indicate Nature of Notice,	Panart or Other Data
12. Check Ap	opropriate box to indicate reature of reolice,	, Report of Other Data
NOTICE OF INT	FINTION TO: SUE	SSEQUENT REPORT OF:
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK DALTERING CASING REMEDIAL WORK DALTERING CASING		
TEMPORARILY ABANDON	_	RILLING OPNS. P AND A
	<u> </u>	<u>—</u>
	MULTIPLE COMPL CASING/CEMEN	11 JOB 🔲
DOWNHOLE COMMINGLE		
CLOSED-LOOP SYSTEM	□ OTHER:	TA STATUS W/CHART
OTHER:		IA STATUS WICHART KI
13. Describe proposed or comple	ted operations. (Clearly state all pertinent details, ar	nd give pertinent dates, including estimated date
13. Describe proposed or comple of starting any proposed work	ted operations. (Clearly state all pertinent details, ark). SEE RULE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated date
13. Describe proposed or comple	ted operations. (Clearly state all pertinent details, ark). SEE RULE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated date
13. Describe proposed or comple of starting any proposed work proposed completion or recompletion or recompletion.	sted operations. (Clearly state all pertinent details, and k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
13. Describe proposed or comple of starting any proposed work proposed completion or recompletion or recompletion.	ted operations. (Clearly state all pertinent details, ark). SEE RULE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
13. Describe proposed or comple of starting any proposed work proposed completion or recompletion of the completion of t	ted operations. (Clearly state all pertinent details, and k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. TO 600 PSI FOR 30 MINUTES. ORIGINAL MIT C	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
13. Describe proposed or comple of starting any proposed work proposed completion or recompletion or recompletion.	ted operations. (Clearly state all pertinent details, and k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. TO 600 PSI FOR 30 MINUTES. ORIGINAL MIT C	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
13. Describe proposed or comple of starting any proposed work proposed completion or recompletion of the completion of t	ted operations. (Clearly state all pertinent details, and k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. TO 600 PSI FOR 30 MINUTES. ORIGINAL MIT CABANDONED.	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
13. Describe proposed or comple of starting any proposed work proposed completion or recompletion of the completion of t	ted operations. (Clearly state all pertinent details, and k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. TO 600 PSI FOR 30 MINUTES. ORIGINAL MIT CABANDONED.	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
13. Describe proposed or comple of starting any proposed work proposed completion or recompletion of the completion of t	ted operations. (Clearly state all pertinent details, and k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. TO 600 PSI FOR 30 MINUTES. ORIGINAL MIT CABANDONED.	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
13. Describe proposed or comple of starting any proposed work proposed completion or recompletion of the completion of t	ted operations. (Clearly state all pertinent details, and k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. TO 600 PSI FOR 30 MINUTES. ORIGINAL MIT CABANDONED.	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
13. Describe proposed or comple of starting any proposed work proposed completion or recompletion of the proposed completion of t	eted operations. (Clearly state all pertinent details, and k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. TO 600 PSI FOR 30 MINUTES. ORIGINAL MIT COMBANDONED.	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
13. Describe proposed or comple of starting any proposed work proposed completion or recompletion of the completion of t	ted operations. (Clearly state all pertinent details, and k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. TO 600 PSI FOR 30 MINUTES. ORIGINAL MIT CABANDONED.	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
13. Describe proposed or comple of starting any proposed work proposed completion or recompletion of the proposed completion of t	eted operations. (Clearly state all pertinent details, and k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. TO 600 PSI FOR 30 MINUTES. ORIGINAL MIT COMBANDONED.	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
13. Describe proposed or comple of starting any proposed work proposed completion or recompletion of recomplet	ABANDONED. Rig Release Date:	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of CHART AND COPY IS ATTACHED.
13. Describe proposed or comple of starting any proposed work proposed completion or recompletion of recomplet	eted operations. (Clearly state all pertinent details, and k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. TO 600 PSI FOR 30 MINUTES. ORIGINAL MIT COMBANDONED.	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of CHART AND COPY IS ATTACHED.
13. Describe proposed or comple of starting any proposed work proposed completion or recompletion of recomplet	ABANDONED. Rig Release Date:	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of CHART AND COPY IS ATTACHED.
13. Describe proposed or comple of starting any proposed work proposed completion or recompletion of recomplet	ABANDONED. Rig Release Date:	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of CHART AND COPY IS ATTACHED.
13. Describe proposed or complete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of the starting any proposed work proposed completion or recomplete of the starting any proposed work proposed completion or recomplete of the starting any proposed work propos	ted operations. (Clearly state all pertinent details, ark). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. TO 600 PSI FOR 30 MINUTES. ORIGINAL MIT CABANDONED. 6/24/2020 Rig Release Date:	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of CHART AND COPY IS ATTACHED.
13. Describe proposed or comple of starting any proposed work proposed completion or recompletion or recompletion of recompletion of recompletion of recompletion of recompletion of the starting of the start	Rig Release Date:	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of CHART AND COPY IS ATTACHED.
13. Describe proposed or comple of starting any proposed work proposed completion or recompletion of recomplet	ted operations. (Clearly state all pertinent details, ark). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. TO 600 PSI FOR 30 MINUTES. ORIGINAL MIT CABANDONED. 6/24/2020 Rig Release Date:	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of CHART AND COPY IS ATTACHED. ge and belief.
13. Describe proposed or comple of starting any proposed work proposed completion or recompletion or recompletion of recompletion of recompletion of recompletion of recompletion of the starting any proposed work proposed completion or recompletion of the starting any proposed work	TITLE PERMITTING S	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of CHART AND COPY IS ATTACHED. ge and belief. SPECIALIST DATE 06/4/2020
13. Describe proposed or complete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of the starting any proposed work proposed completion or recomplete of the starting any proposed work proposed completion or recomplete of the starting any proposed work propos	Rig Release Date:	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of CHART AND COPY IS ATTACHED. ge and belief. SPECIALIST DATE 06/4/2020
13. Describe proposed or comple of starting any proposed work proposed completion or recompletion or recompletion of recompletion of recompletion of recompletion of recompletion of the starting any proposed work proposed completion or recompletion of the starting any proposed work	TITLE PERMITTING S	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of CHART AND COPY IS ATTACHED. ge and belief. SPECIALIST DATE 06/4/2020
13. Describe proposed or complete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of STATE CASING WELL IS TEMPORARILY CURRENT TA EXPIRES OF STATE OF	RA-MURILLO E-mail address: Cherreramurillo@	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of CHART AND COPY IS ATTACHED. Ge and belief. SPECIALIST DATE 06/4/2020 Schevron.com PHONE: 575-263-0431
13. Describe proposed or complete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of the starting any proposed work proposed completion or recomplete of the starting any proposed work proposed completion or recomplete of the starting any proposed work propos	TITLE PERMITTING S	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of CHART AND COPY IS ATTACHED. ge and belief. SPECIALIST DATE 06/4/2020

