

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-24047
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	857947
7. Lease Name or Unit Agreement Name	NORTH VACUUM ABO WEST UNIT
8. Well No.	16
9. Pool Name or Wildcat	VACUUM ABO, NORTH
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	4068' GL

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.	
1. Type of Well:	OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER INJECTION
2. Name of Operator	CHEVRON USA INC
3. Address of Operator	15 SMITH RD, MIDLAND, TX 79705
4. Well Location	Unit Letter <u>F</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>1980</u> Feet From The <u>WEST</u> Line Section <u>28</u> Township <u>17S</u> Range <u>34E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	4068' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPERATION <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input checked="" type="checkbox"/> TEMPORARILY ABANDON

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-12-06: MIRU. TIH W/CCL & GUNS TO SHOOT 4 HOLES @ 8396'.
9-13-06: WELL PRESSURE TBG 225#, CSG-1700#. BLEED PRESS OFF. PMP 120 BBLS 14.3% MUD DN TBG. WELL DEAD. PMP 65 BBLS 14.5# MUD DN TBG.
9-14-06: REL PKR. TIH W/BIT & TBG TO 8521'. EOT@ 7788'.
9-15-06: TIH W/CIBP & SET @ 8450'. DUMP 1 SX CMT ON CIBP. TIH W/PKR, SN, & 220 JTS 2 3/8" TBG TO 7029'. COULDN'T GET PKR TO GO DN. CIRC MUD OUT FR 6965'. TOH W/TBG TO 6325'.
9-18-06: TIH W/2 3/8" TBG TO 8408'. CIRC MUD OUT. TEST CIBP TO 500#-G00D. DISPL W/200 BBLS PKR FLUID.
9-19-06: RUN CHART FOR NMOC. TEST CSG TO 640# FOR 35 MINUTES. NO LOSS. RIG DOWN. (ORIGINAL CHART & COPY OF CHART ATTACHED).
FINAL REPORT

WELL IS TEMPORARILY ABANDONED.

This Approval of Temporary
Abandonment Expires 9/19/11

Received
9/27/06

I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE <u>Denise Pinkerton</u>	TITLE <u>Regulatory Specialist</u>
DATE <u>9/27/2006</u>	Telephone No. <u>432-687-7375</u>
TYPE OR PRINT NAME <u>Denise Pinkerton</u>	

(This space for State Use)	APPROVED <u>Gay W. Wink</u>	TITLE <u>OC FIELD REPRESENTATIVE II/STAFF MANAGER</u>	DATE <u>SEP 02 2006</u>
CONDITIONS OF APPROVAL, IF ANY:			

