

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division
1625 N. French Dr.
Hobbs, NM 88240

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.
LC-032579E

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.
CARLSON B-25 FED #3

9. API Well No.
30-025-11783

10. Field and Pool, or Exploratory Area
JUSTIS ABO

11. County or Parish, State
**LEA COUNTY
NEW MEXICO**

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well
 Oil Well Gas Well Other

2. Name of Operator
HENRY PETROLEUM LP

3a. Address
3525 ANDREWS HWY, MIDLAND, TX 79703-5000

3b. Phone No. (include area code)
(432)694-3000


4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
**O - 990' FSL & 1650' FEL
SEC. 25-T25S-37E**

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/ Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input checked="" type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other _____
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

1. POOH with rods and tubing
2. PU workstring and prepare to frac stimulate the well (no additional perforating)
3. Flow back CO2 and fluids to a frac tank after the stimulation while monitoring for safety and sellable gas to turn back to the pipeline
4. TIH with rods and tubing
5. Put well back on production



14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)
SHIRLEY HOUCHINS

Signature
Shirley Houchins

Title
REGULATORY SPECIALIST

Date
11/17/2003

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by *Chris Williams* OC DISTRICT SUPERVISOR Title GENERAL MANAGER Date **DEC 01 2003**

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office