

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Gulf Oil Corporation</b>	8. Farm or Lease Name <b>H. L. Vinson</b>
3. Address of Operator <b>P.O. Box 98; Andrews, Texas 79714</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>A</b> <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>East</b> LINE, SECTION <b>22</b> TOWNSHIP <b>9-S</b> RANGE <b>36-E</b> NMPM.	10. Field and Pool, or Wildcat <b>Crossroads (Penn)</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4057' DF</b>	12. County <b>Lea</b>


16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data


NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On 12-16-69 ran Guiberson type "BL" Anchor Assembly bull-plugged on bottom and latch into pkr @ 9566'. Hole was loaded with 10# plus mud. Dumped 2 sacks sand and 2 sacks cement on top of plug with dump bailer. Rigged down pulling unit. Rigged up casing puller unit 12-19-69. Shot 7" casing at 5680' and worked free. Pulled 7" csg and rigged down. Rigged up pulling unit 12-26-69. Ran 2 7/8" tbg and spotted 25 sack cement plug 5722' to 5660' and 40 sack cement plug 4220 to 4120'. Cut off head and spotted 18 sack cement plug 50' to surface. Installed marker and cleaned up location. Left following pipe in well: 13 3/8" - 374'; 9 5/8" - 4194'; 7" - 4030'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED  TITLE Area Engineer DATE 3-26-70

APPROVED BY  TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: