

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Tenneco Oil Company 3. Address of Operator 6800 Park Ten Blvd., Suite 200 North, San Antonio, Texas 78213 4. Location of Well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>12</u> TOWNSHIP <u>9S</u> RANGE <u>34E</u> NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 4221.3 GR	7. Unit Agreement Name 8. Farm or Lease Name Ward Insall Com 9. Well No. 1 10. Field and Pool, or Wildcat Vada Penn 12. County Lea
----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pulled rods, pump, tubing & anchor.
2. Set CIBP @ 9700'.
3. Spot 100' of Class "C" cement on top of bridge plug to 9600'.
4. Set 10 sack cement plug @ 6713'.
5. Set 10 sack cement plug @ 4050'.
6. Set CIBP @ 415'.
7. Pumped cement from 415' to surface.
NOTE: 9.5 ppg salt mud between all plugs.
8. Erected P & A marker
7. Cleaned location and cut off mast anchors.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Robert C. Mather TITLE Production Engineering Suprv. DATE May 6, 1982

APPROVED BY Jack Griffin TITLE OIL & GAS INSPECTOR DATE JAN 2 1987

CONDITIONS OF APPROVAL, IF ANY: