

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 065510

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back ~~into~~ different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

FEDERAL 1122"

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

GOOD SAN ANDRES

11. SEC. T., E., M., OR NE. AND SURVEY OR S&W

22-TS-R35E

12. COUNTY OF PARISH, IS. STATE

ROOSEVELT NEW MEXICO

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR
JACK L. McCLELLAN

3. ADDRESS OF OPERATOR
Box 848, ROSWELL, NEW MEXICO

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

990' FSL & 1650' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4208.5 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIR WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT

(Other)

SEGREGATE GAS ZONES

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log forms)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12/20/66 KILLED WELL & PULLED TUB. RE-RAN TUB. & SET PKR. AT 4197'. TO SEPERATE THE "A" ZONE FROM THE "B" ZONE. TESTED "B" ZONE. WEAK BLOW OF GAS. WELL PROBABLY WATER LOGGED.

12/21/66 PULLED TUB. & SET BRIDGE PLUG @ 4195'. PERF. CSG. 1 SHOT/FT. AT 4158, 4160, 4168, 4170, 4180, 4182, & 4184, ALL IN THE "A" ZONE. SWB. LOAD WTR. HARD BLOW OF GAS.

12/22/66 FL 1500'. SWB. DOWN. ACIDIZED W/1000 GALS. (4158-4184). SWB LOAD. FAIR TO GOOD BLOW OF GAS.

12/27/66 PULLED TUG. AND DRILLED OUT BRIDGE PLUG AT 4195'. RE-RAN TUBING AND SET PACKER AT 4195'.

ALTERNATELY TESTED "A" & "B" ZONE THROUGH TUBING AND CASING ANNULAS, TO ASCERTAIN WHICH ZONE PRODUCED MOST GAS.

WELL NOW PRODUCING GAS FROM THE "B" ZONE THROUGH THE TUBING, "A" ZONE SHUT-IN. PRESSURES ON TUBING AND CASING INDICATE THAT THE TWO ZONES ARE EFFECTLY SEPERATED.

18. I hereby certify that the foregoing is true and correct

SIGNED

Jack L. McClellan

TITLE

Operator

DATE

3/15/67

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

This form is to be filled out by the operator of a well and submitted to the nearest office of the Bureau of Land Survey for the State in which the well is located.

NAME OF OPERATOR
JACK L. McQUEEN

ADDRESS OF OPERATOR
Box 418, Forestburg, Ark.

LOCATION OF WELL
See also page 17 below.

PERMIT NO.

DATE

STATE

COUNTY

TOWNSHIP

RANGE

SECTION

NEED FOR WATER

REASON FOR ABANDONMENT

DATE OF ABANDONMENT

REASON FOR ABANDONMENT

DATE OF ABANDONMENT

REASON FOR ABANDONMENT

DATE OF ABANDONMENT

REASON FOR ABANDONMENT

DATE OF ABANDONMENT

REASON FOR ABANDONMENT

DATE OF ABANDONMENT

REASON FOR ABANDONMENT

DATE OF ABANDONMENT

REASON FOR ABANDONMENT

DATE OF ABANDONMENT

REASON FOR ABANDONMENT

DATE OF ABANDONMENT

REASON FOR ABANDONMENT

DATE OF ABANDONMENT

REASON FOR ABANDONMENT

DATE OF ABANDONMENT

REASON FOR ABANDONMENT

DATE OF ABANDONMENT

REASON FOR ABANDONMENT

DATE OF ABANDONMENT

REASON FOR ABANDONMENT

DATE OF ABANDONMENT

REASON FOR ABANDONMENT

DATE OF ABANDONMENT

REASON FOR ABANDONMENT

DATE OF ABANDONMENT

REASON FOR ABANDONMENT

DATE OF ABANDONMENT

Instructions

General: This form is designed for submitting proposals to perform certain well operations and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by the State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices either are shown below or will be issued by or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 7: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of putting of any casing liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well was conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1953 O-948228

See Instructions on Reverse Side

[Signature]

[Signature]