Form 3160-5 (August 1999)

## UNITED STATES DEPARTMENT OF THE INTERIOR BURFALLOF LAND MANAGEMENT

N.M. Oil Cons. Division No. 1004-0135 Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS Hobbs, NM & Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.						§											
SUBMIT IN TRIPLICATE - Other instructions on reverse side  1. Type of Well  Gas Well Other  2. Name of Operator					7. If Unit or CA/Agreement, Name and/or No.  8. Well Name and No. Bluitt SA 13 Federal #7												
									SAGA PETROLEUM LLC  3a. Address 3b. Phone No. (include area code)						9. API Well No. 30-041-20159		
									415 W WALL, SUITE 1900 MIDLAND, TX 79701 (915)684-42					10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1980' FNL & 1980' FEL Sec 13 (G) T8S, R37E					Bluitt San Andres Assoc  11. County or Parish, State Roosevelt NM												
12. CHECK AF	PROPRIATE BOX(ES) T	O INDICAT	E NATURE	OF NOTICE, F	REPORT. (	OR OT	HER DATA										
TYPE OF SUBMISSION	TYPE OF ACTION																
<ul><li>☒ Notice of Intent</li><li>☐ Subsequent Report</li><li>☐ Final Abandonment Notice</li></ul>	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	Deepen Fracture New Con Plug and Plug Bacl	struction $\overline{X}$ Abandon	Reclamation Recomplete Temporarily Aba	,		Water Shut-Off Well Integrity Other										
13. Describe Proposed or Completed	d Operation (clearly state all pertin	ent details, inclu-	ding estimated st	arting date of any pr	onosed work :	and appro	oximate duration	thereof									
If the proposal is to deepen direct Attach the Bond under which the following completion of the invotesting has been completed. Final determined that the site is ready:  Intend to recomplete this Sqz P2 perfs by mixing & w/0.3% FLA. Perf 14 ho pad, 8000 gal 30# borate @ AIR 12 BPM, max presback to frack tank to kick gauge & run 4 point CAO!  PLEASE SU WHEN WOR	tionally or recomplete horizentally a work will be performed or provide lived operations. If the operation relabandonment Notices shall be fit for final inspection.)  SI WIW to the P1 San Adpumper into the P2 San Apples in the P1 San Andrew xlink gel (in 4/2000 galls so 4500#, estimated avgoff well. Flow to atmosp F test. Connect to sales  BMIT 3160-4 COMPLETER IN THE SAND WELL	y, give subsurface the Bond No. of esults in a multip, led only after all Andres as a Andres perfs es from 4520 estages) w/1- treat press there until w line.  TION REPO	e locations measure file with BLM le completion or requirements, incompletion of the completion of the	red and true vertica /BIA. Required sub- recompletion in a ne- cluding reclamation, comt retainer 75 rac Procedure: or 16/30 sand l overnight to	5 sx Prems Pump 50 d. Flush to break gel, up, SI for	pertinents shall be Form 316 mpleted, nium P 2000 gall be btm p RIH w 72-96	t markers and zore filed within 30 50-4 shall be filed and the operator lus (Class Cl 30# borate perf w/2% slip/swab, swall hrs, RIH w/E	nes. days once has  ) cmt xlink gel ck KCL b well									
Name (Printed Typed)  Bonnie Husband			Title	TION ANALY	ST			K									
Signatur			Date														
Honnes Styr	tand)		11/13/200		220750000000000000000000000000000000000	of endedic RMM	tgalue, Leestroon shirinka .										
	IHIS SPACE	FUN FEDER		re office us	<b>-</b>												
Approved by			Title			Date											
Conditions of approval, if any, are at	tached. Approval of this notice do	es not warrant o	Office	;		·		14.6									

certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.