NO. OF COPIES RECEIVED		Form C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Supersedes Old C+102 and C-103
FILE	THE MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State Fee Y
OPERATOR		5. State Oil & Gas Lease No.
		233 233 2333 110.
	SUNDRY NOTICES AND REPORTS ON WELLS A FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
OIL GAS WELL	OTHER- Salt Water Disposal	7. Unit Agreement Name
2. Name of Cyerator		8, Farm or Lease Name
3. Address of Operator	ada Hess Corporation	Bagley S.W.D.
•		9. Well No.
4. Location of Well	er "D", Monument, New Mexico 88265	2
	((0	IC. Field and Pool, or Wildcat
UNIT LETTER	. 660 FEET FROM THE North LINE AND 1980 FEET FROM	Bagley Penn
THE West	11 10.0 00.7	
THE WOOD LINE	E, SECTION 11 TOWNSHIP 12-S RANGE 33-E NMPM	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	4249' DF	
^{16.}		Lea
NOTICE	heck Appropriate Box To Indicate Nature of Notice, Report or Ot	
	SUBSEQUEN	T REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	ALTERING CASING
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
	OTHER	_
OTHER		
17. Describe Proposed or Comp	eted Operations (Clearly state all particular)	
work) SEE RULE 1103.	leted Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any propose
	d tubing and packer. Set C.I. bridge plug at 8900.	
	t on top of plug. Filled hole w/SW mud. Cut 5-1/2	
	ed 70 sx. cement plug from 3810' to 3603'. Cut 7-5/8	
	ed 70 sx. cement plug from 806' to 671', 70 sx. cemen	
2981 8	20 sx. plug from 24' to surface. Installed dry hol	le marker.
Well I	Plugged and Abandoned.	
 .		
8. I hereby certify that the infor	mation above is true and complete to the best of my knowledge and belief.	

Supver., Admin. Services

6-13-73