					•	
COPIES REC						Form C-103 Supersedes Old C-102 and C-103
FE		NE	MEXICO OIL CON	SERVATION CON	AMISSION	Effective 1-1-65
E						Control Type of Logge
U.S.G.S.						State Fee X
LAND OFFICE						5. State Oil & Gas Lease No.
OPERATOR						
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BIG. TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.						7. Unit Agreement Name
1.	GAS					7. Onit Agreement Nume
2. Name of Operator						8. Farm or Lease Name
GENERAL PETROLEUM, INC.						Z TAYLOR
3. Address of Oper	ator	W 0/0 H	OBBC NILD MEY	rco 88240		9. Well No.
		X 840 - H	OBBS, NEW MEX	100 80240		10. Field and Pool, or Wildcat
4. Location of Well		660	FROM THE NORTH		1980	GLADIOLA - WOLFCAMP
UNIT LETTER	,_	FEET	FROM THE	LINE AND	1780 PEET FROM	
ËA	ST	7	TOWNSHIP	2 RANSS	38 <sub>NMPM</sub>	
THE	LINE, SE					
		15.	Elevation (Show wheth	er DF, RT, GR, etc	•2	12. County
			3885 D.F.		. D O	LEA COMMINION
16.			Box To Indicate	Nature of Not	ice, Report or Ot	ner Data T REPORT OF:
	NOTICE OF	F INTENTION T	0:		30532432	
PERFORM REMEDIA	L WORK		PLUG AND ABANDON	REMEDIAL WORK	· 🔲	ALTERING CASING
TEMPORARILY ABAI	=		_	COMMENCE DRIV	ING OPNS.	PLUG AND ABANDONMENT
CHANGE PLANS CASING TEST AND CEMENT JOB						EFCAM X
			_	OTHER P	LUG BACK TO WO	JEF CAPY
OTHER					_	
17. Describe Prop	oosed or Complete	ed Operations (Clea	rly state all pertinent o	letails, and give po	ertinent dates, includin	g estimated date of starting any proposed
work) SEE RI	JLE 1103.					
7-16-75	Set Bridg	e Plug @1041	12'.			
Tested Tubing to 4,000#.  Spotted Acid from 10167' to 9067' - Should hav						m 9500 to 9000.
	Spotted A	cid from 10:	take in adding	- SHOULG	UMAE DEGIT 1104	a 7500 to 7000.
	Had MADE	d from 9490	to 9494.	, tally a		
	Perrorace	d IIom >4>0	20 74744			
7 <b>-23-7</b> 5	Ran Guibe	rson Unipac	ker 6 & pump c	avity on 15	2 stands tubi	ag.
		-				