

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

HOGBS OFFICE O.C.C.  
NEW MEXICO OIL CONSERVATION COMMISSION  
JUN 9 10 54 AM '69

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name <b>Miller</b>	
9. Well No. <b>1</b>	
10. Field and Pool, or Wildcat <b>Gladiola Devonian</b>	
12. County <b>Lea</b>	

### SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator <b>Cities Service Oil Company</b>	
3. Address of Operator <b>P. O. Box 69 - Hobbs, New Mexico 88240</b>	
4. Location of Well UNIT LETTER <b>J</b> <b>1980</b> FEET FROM THE <b>South</b> LINE AND <b>1980</b> FEET FROM THE <b>East</b> LINE, SECTION <b>18</b> TOWNSHIP <b>12S</b> RANGE <b>38E</b> NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.) <b>3885 DF</b>	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The above well was plugged and abandoned in the following manner:

Loaded hole w/mud laden fluid. Set CI bridge plug @ 11900' w/5 sack cement plug on top. Cut 5½ csg. @ 9600' and set 25 sack plug ½ in and ½ out of casing stub. Set 25 sack cement plugs @ 7208-7108, 6584-6484, 7899-7799 and 5963-5863. Set 25 sack cement plug @ 4505-4455, ½ in and ½ out of 8 5/8" casing. Set @ 4480. Intermediate cement was circulated thru top of San Andres @ 4450. Set 10 sack surface plug with 4' marker extending 4' above ground. Location has been cleaned of all equipment, debris and the pits and cellars have been filled and levelled.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED \_\_\_\_\_

TITLE **District Office Manager**

DATE **June 6, 1969**

APPROVED BY *John W. Remy*  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

DATE \_\_\_\_\_