DISTRICT

DISTRICT] P.O. Box 1980, Hobba 17M 88240

OIL CONSERVATION DIVISION

P.O. Box 2088 Santa Fe, New Mexico 87504-2088

WELL AM NO. 30252235700	
5. Indicate Type of Lease STATE X	ree [

F.O. Drawer DD, Artesia, NM \$8210 DISTRICTIII

STATE & State Oil & Gas Lease No.

K-4177	
W Unit Agreement Name	
1	
Wildcat (U. Penn)	
om The West Line	
Lea County	
er Data REPORT OF:	
ALTERING CASING PLUG AND ABANDONMENT	
) *	
te of starting any proposed	
1 14	

- work) SEE RULE 1103.
- POOH with pump, rods and tubing.
- Set CIBP at 9730' (current perfs are 9882'-88', 9774'-82'). 2.
- Dump 35' of cement on CIBP to permanently abandon Bough "B" and Bough "C" perfs. 3.
- Perf Upper Penn from 9066'-71' and 9074'-81' with 2 JSPF.
- GIH with treating packer on workstring, set packer at 8980' and acidize perfs with 2500 gal 20% NEFE.
- Return well to production.

Thereby certify that the information shore is true and complete to the best of my knowledge Santh. Santh. Robby J. Smith	ge and belief.	Sr. Petroleum Engineer	DATEIan31,1992
(This space for Suca Uni) (This space for Suca Uni) (This space for Suca Uni)	TIII -		FEB 1 0.92
ATTROYED BY			