

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-25173
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 1-522
7. Lease Name or Unit Agreement Name Lea "YN" State
8. Well No. 2
9. Pool name or Wildcat Tulka Penn
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Smith & Marrs Inc.
3. Address of Operator P.O. Box 863 Kermit Tx. 79745
4. Well Location Unit Letter K : 1980 Feet From The South Line and 1980 Feet From The West Line Section 27 Township 14S Range 32E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-15-1991 Set CIBP @ 9,700' dump 35' cement on top
4-17-1991 Spot 40 sxs cement @ 8050'-7900' tagged
4-17-1991 Spot 40 sxs @ 5050'-4900'
4-17-1991 Spot 40 sxs @ 4150'-4050' tagged
4-22-1991 Spot 45 sxs @ 1210'-1096' tagged
4-22-1991 Spot 60 sxs @ 437'-300' tagged
4-22-1991 Spot 10 sxs @ surface

Install dry hole marker
Hole circulated with 10# mud
Pulled 8000' of 4 1/2' casing
Pulled 1156' of 8 5/8" casing

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rickey Smith TITLE V-P DATE 6-3-91

TYPE OR PRINT NAME Smith + MARRS INC Rickey Smith TELEPHONE NO. 915-586 3076

(This space for State Use)

APPROVED BY Billy P. Smith TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUN 05 1991

1000
HQSBS OFFICE