

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE ?	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.		
OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. Unit Agreement Name
Name of Operator		McDonald Unit
Harvey E. Yates Company		8. Farm or Lease Name
Address of Operator		9. Well No.
P.O. Box 1933, Roswell, New Mexico 88201		1
Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER <u>P</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>990</u> FEET FROM		McDonald Upper Penn
THE <u>East</u> LINE, SECTION <u>33</u> TOWNSHIP <u>13S</u> RANGE <u>36E</u> NMPM.		
11. Elevation (Show whether DF, RT, GR, etc.)		12. County
3951' GR		Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
FULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	
		OTHER ☐	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-28-87 Set 5 1/2" CIBP @ 10,000' w/35' cmt on top.
 7-29-87 Displace hole w/salt gel mud. Spot 25 sxs, 100' plug from 9744' to 9644'.
 7-30-87 Free point csg @ 7172'.
 7-31-87 Shot collar @ 7172'. POH laying down 179 jts 5 1/2" csg.
 8-1-87 Spot 35 sxs plug @ 7231'. Tag plug @ 7024'. Spot 35 sxs plug from 4611 to 4511.
 8-2-87 Tag top of plug @ 4419'. Spot 35 sxs plug from 2229 to 2129'. Spot 10 sxs plug @ surface.
 Install dry hole marker. P & A complete.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Ray L. Smith</u>	TITLE <u>Production Manager/Engineer</u>	DATE <u>August 10, 1987</u>
APPROVED BY <u>Gusman Smith</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>AUG 10 '88</u>

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
AUG 11 1987
OCD
HOBBS OFFICE