

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

JUL 28 11 43 AM '69

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name S. B. Rose
9. Well No. 1
10. Field and Pool, or Wildcat Undesignated - Abo
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Amerada Hess Corporation
3. Address of Operator P. O. Box 1920 - Hobbs, New Mexico
4. Location of Well UNIT LETTER F 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 35 TOWNSHIP 16-S RANGE 38-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3705' DF

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set bridge plug at 10,000' with 1 sack cement on top. Perforate Abo Zone 9180' to 9190' with 2 shots per foot, total of 20 holes. Acidized perfs. 9180' to 9190' with 4500 gals. 15% acid. Tested 8 bbls. oil with 27% water in 24 hrs. Set packer with expendable plug at 6700' with 2 sacks sand on top. Perforated 5-1/2" casing at 6532' with 2 holes and squeezed with 150 sacks cement. Drilled out to 6511'. Perforated 5-1/2" casing in Paddock Zone with 1 shot per foot from 6410' to 6427', 6460' to 6466', and 6472' to 6500'. Total of 54 holes. Acidized perfs. 6410' to 6500' with 1000 gallons mud acid. Swab test - 24 hrs - 0 bbls. oil and 67 bbls. water.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *[Signature]* TITLE **District Clerk** DATE **July 28, 1969**
APPROVED BY *[Signature]* TITLE DATE
CONDITIONS OF APPROVAL, IF ANY: