

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88240
DISTRICT II
P.O. Drawer DD, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-29816
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FREE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-2229
7. Lease Name or Unit Agreement Name	PHILLIPS E STATE
8. Well No.	35
9. Pool name or Wildcat	MALJAMAR GB/SA
4. Well Location	Unit Letter <u>K</u> : <u>1880</u> Feet From The <u>SOUTH</u> Line and <u>1880</u> Feet From The <u>WEST</u> Line
Section <u>14</u> Township <u>17 S</u> Range <u>33 E</u> NMPM <u>LEA</u> County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4135' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
Phillips Petroleum Company

3. Address of Operator
4001 Penbrook Street, Odessa, TX 79762

4. Well Location
Unit Letter K : 1880 Feet From The SOUTH Line and 1880 Feet From The WEST Line
Section 14 Township 17 S Range 33 E NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4135' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3/1/95 MIRU DDU. NU BOP. RIH W/5-1/2" CIBP ON 2-3/8" WORKSTRING, SET @4356'.
3/2/95 CIRC. HOLE W/10 PPG MUD-LADEN BRINE. PRESSURED CASING TO 500 PSI-OK. PUMP PLUG #1 ON ON TOP OF CIBP 4356'-3956', 40 SX CLASS C CMT. PUMP PLUG #2 3785'-3535', 25 SX CLASS C CMT. PUMPED PLUG #3 2782'-2532', 25 SX CLASS C CMT. PUMP PLUG #4 1593'-1343', 25 SX CLASS C CMT. PUMP PLUG #5 240'-SURF, 25 SX CLASS C CMT. CIRCULATED CMT TO SURF. ND BOP. RDMO DDU. WELLBORE IS P&A'D.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. M. Sanders TITLE SUPERVISOR, REG. AFFAIRS DATE 3/9/95

TYPE OR PRINT NAME L. M. SANDERS TELEPHONE NO. 915/368-1488

(This space for State Use)

APPROVED BY Larry W. Hiep TITLE OIL & GAS INSPECTOR DATE AUG 23 1995

CONDITIONS OF APPROVAL, IF ANY: