

OIL CONSERVATION DIVISION

310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-33270
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-2148
7. Lease Name or Unit Agreement Name Caprock Maljamar Unit
8. Well No. 207
9. Pool name or Wildcat
10. Elevation (Show whether DF, RKB, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well
Oil Gas
Well Well OTHER

2. Name of Operator
The Wiser Oil Company

3. Address of Operator
8115 Preston Road, Suite 400, Dallas, TX 75225

4. Well Location
Unit Letter O Section 19 Township 17S Range 33E NMPM Feet From The South Line and 1404 Feet From The East Line
County Lea

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: Perf & acidize <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operation (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

04/03/96 Perforate @ 4572, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, (11 holes). Acidize perms 4572-4582' w/2000 gals 15% NEFE acid. Set CIBP @ 4563'.

04/08/96 Perforate @ 4495-4529'. Acidize perms 4495-4529' w/3000 gals 15% NEFE acid. Set CIBP @ 4470'.

04/11/96 Perforate 4333, 34, 35, 36, 37, 38, 39, 40 & 53' (9 holes). Acidize perms 4333-4353' w/1500 gals 15% NEFE acid.

05/06/96 Perforate 4059-4265'. Acidize perms 4059-4265' w/3500 gals 15% NEFE acid.

05/08/96 Frac perms 4059-4353' w/ 83,958 gal Boragel-C w/139,900# 16/30 Brown Sand

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Betty Epie TITLE Production Administrator DATE 7/16/96

TYPE OR PRINT NAME Betty Epie TELEPHONE NO. (214)265-0080

(THIS SPACE FOR STATE USE)

APPROVED BY _____ TITLE _____ DATE AUG 20 1996

CONDITIONS OF APPROVAL, IF ANY: