

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIP
(Other instructions
reverse side)

VE*
re

5. LEASE DESIGNATION AND SERIAL NO.

LC 064198A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL GAS WELL OTHER

7. UNIT AGREEMENT NAME

Lusk Deep Unit

2. NAME OF OPERATOR

El Paso Products

8. FARM OR LEASE NAME

Lusk Deep Unit

3. ADDRESS OF OPERATOR

c/o Hobbs Pipe & Supply Company, Box 2010, Hobbs, N.M.

9. WELL NO.

2

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FSL & 1980' FEL

10. FIELD AND POOL, OR WILDCAT

Lusk Strawn

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec.18, T19S, R32E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3585'

12. COUNTY OR PARISH

Lea

13. STATE

N. M.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Propose to spot a 20 sx cement plug at 12,350'.
2. Propose to spot a 35 sx cement plug at 11,200'.
3. Propose to spot a 35 sx cement plug at stub of 9-5/8 casing at 8990'.
4. Propose to spot a 35 sx cement plug at 7000' at Bone Springs.
5. Propose to spot a 35 sx cement plug at base of 13-3/8 at 4462'.
6. Propose to spot a 35 sx cement plug at 2900'.
7. Propose to spot a 10 sx cement plug at surface with marker.
8. Hole will be loaded with mud-laden fluids.

18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

TITLE

Agent

DATE


8/16/71

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE



*See Instructions on Reverse Side

RECEIVED

AUG 2 1971

OIL CONSERVATION COMMISSION
HOBBBS, N.M.