

NO. OF COPIES RECEIVED	
DISTRIBUTION	
ALTA FE	
FILE	
J.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No. <i>B-1520</i>	
7. Unit Agreement Name	
8. Farm or Lease Name <i>Bridge Gate</i>	
9. Well No. <i>51</i>	
10. Field and Pool, or Wildcat <i>Vac (H-SA)</i>	
12. County <i>Lea</i>	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER- *WIW*

2. Name of Operator
Mobil Oil Corporation

3. Address of Operator
Box 633, Midland, Texas 79701

4. Location of Well
UNIT LETTER *M* *660* FEET FROM THE *South* LINE AND *660* FEET FROM THE *West* LINE, SECTION *12* TOWNSHIP *17-S* RANGE *34-E* NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
4038 GR.

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plug & abandon as per attached Procedure

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <i>Christine D. Tucker</i>	TITLE <i>Peroration Clerk</i>	DATE <i>1-5-73</i>
Orig. Signed by <i>Joe D. Ramsey</i>		
APPROVED BY <i>Dir. L. S. S. S.</i>	TITLE	DATE

CONDITIONS OF APPROVAL, IF ANY:

WELL WORK RECOMMENDATIONS
Proposals for Well Reconditioning and Subsurface Maintenance
Workovers, Expense DD's, PB's, and Conversions

Lease: BRIDGES STATE Well No. W.I.W #51
Field: VACUUM- SAN ANDRES FLOOD
County: LEA State: NEW MEXICO

RECOMMENDED PROCEDURE:

- 1 - M.T.P.U. PULL CEMENT LINED TUBING & PKR.
- 2 - RUN 2" TUBING W/ CEMENT RETAINER. SET RETAINER AT 4300' & SQUEEZE OPEN HOLE.
- 3 - CIRCULATE HOLE TO MUD LADEN FLUID
- 4 - DETERMINE FREE POINT OF 7" CASING. CUT OFF Csg. & PULL
- 5 - SPOT 100' CEMENT PLUG (555x), 50' ABOVE & 50' BELOW CUT OFF POINT
IF CUT OFF POINT IS BELOW 1700' SET ANOTHER PLUG FROM 1700' to 1700'
- 6 - SPOT 100' CEMENT PLUG (505x) FROM 760' to 860'
- 7 - SPOT 105x CEMENT PLUG AT SURFACE
- 8 - CUT OFF WELL HEAD & INSTALL MARKER.

DIAGRAMATIC WELL SKETCH
BRIDGES STATE WELL N: 51
VACUUM- SAN ANDRES FLOOD
LEA COUNTY - NEW MEXICO

