

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO.
30-025-07499

5. Indicate Type of Lease

FED ☐ STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101 FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

Altura Energy Ltd.

3. Address of Operator

1017 W. Stanolind Rd., HOBBS, NM 88240

505/397-8200

4. Well Location

Unit Letter J : 2200 Feet From The South Line and 2310 Feet From The East Line
Section 31 Township 18-S Range 38-E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT GR, etc.)
3642 DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL
WORK ☐

PLUG AND
ABANDON ☐

TEMPORARILY ABANDON ☒

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG & ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Pull production Equipment
- 2) Run in hole with 5" casing scraper to 3950'.
- 3) Run in hole with 5" CIBP and set @3890'. Circ csg with inhibited fluid.
- 4) Test csg to 500# for 30 minutes and chart for the NMOCD.
- 5) Lay down tbg and rig down pulling unit.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Robert N. Gilbert

TITLE Lift Specialist

DATE 1-5-98

TYPE OR PRINT NAME Robert Gilbert

TELEPHONE 505/397-8206
NO.

(This space for State Use)

ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

APPROVED BY

TITLE

DATE

20 1998