

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

MAR 23 3 47 PM '67

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

<p>1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/></p> <p>2. Name of Operator Gulf Oil Corporation</p> <p>3. Address of Operator Box 670, Hobbs, New Mexico</p> <p>4. Location of Well UNIT LETTER F 1650 FEET FROM THE North LINE AND 2310 FEET FROM THE West LINE, SECTION 32 TOWNSHIP 18-S RANGE 38-E NMPM.</p> <p>15. Elevation (Show whether DF, RT, GR, etc.) 3637' OL</p>	<p>5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/></p> <p>5. State Oil & Gas Lease No.</p> <p>7. Unit Agreement Name</p> <p>8. Farm or Lease Name W. D. Grimes (NCT-A)</p> <p>9. Well No. 2</p> <p>10. Field and Pool, or Wildcat Hobbs</p> <p>12. County Lea</p>
--	---

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER Acidise <input type="checkbox"/>	OTHER _____ <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

4155' TD.
Plans have been made to dump 750 gallons of 15% NE acid down tubing over open hole interval 3940' to 4155'. Flush with 15 barrels of oil and return well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ORIGINAL SIGNED BY
SIGNED L. A. TURNER TITLE Area Petroleum Engineer DATE March 23, 1967

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: